



20-Nov-2018

PCN #:E-18-018185

Subject:MSR - relays with CdO contacts. PCN P-18-015849 has already been distributed in advance. See attachement.

Description of Change: The following part numbers are being obsoleted (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application- Drawings are available via TE.com

Reason: Discontinuance. Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.

Key Dates:

Last Order Date:31-Mar-2019

Last Ship/EOL Date:30-Sep-2019

Product Affected

8-1393222-9

(Alias Part Numbers:
"V23061B1004A601")

Recommended Replacement

2-1393222-8

(Alias Part Numbers:
"V23061A1005A602")

1-1393223-5

(Alias Part Numbers:

Product Affected	Recommended Replacement
"V23061B1006A601")	
7-1393222-5 (Alias Part Numbers: "V23061B1002A601")	
4-1416200-5 (Alias Part Numbers: "V23061B1003A401*X60")	3-1416200-8 (Alias Part Numbers: "V23061B1003A301")
4-1416200-5 (Alias Part Numbers: "V23061B1003A401*X60")	6-1416200-4
1-1416200-7 (Alias Part Numbers: "V23061C2005A402")	5-1416200-0 (Alias Part Numbers: "V23061C2005A802")
4-1393223-2 (Alias Part Numbers: "V23061B1010A401")	1416200-9 (Alias Part Numbers: "V23061B1010A301")
4-1393223-2 (Alias Part Numbers: "V23061B1010A401")	7-1416200-0
4-1393223-1 (Alias Part Numbers: "T75S5D112-48" "V23061B1009X 10" "V23061B1009X010")	3-1393223-7 (Alias Part Numbers: "V23061B1009A301")
4-1393223-1 (Alias Part Numbers: "T75S5D112-48" "V23061B1009X 10" "V23061B1009X010")	6-1416200-9
3-1393223-8 (Alias Part Numbers:	3-1393223-7 (Alias Part Numbers:

Product Affected	Recommended Replacement
"V23061B1009A401")	"V23061B1009A301")
3-1393223-8 (Alias Part Numbers: "V23061B1009A401")	6-1416200-9
3-1393223-5 (Alias Part Numbers: "V23061B1008A401")	6-1416200-8
3-1393223-3 (Alias Part Numbers: "V23061B1007X 93")	1-1393223-7 (Alias Part Numbers: "V23061B1007A301")
3-1393223-3 (Alias Part Numbers: "V23061B1007X 93")	6-1416200-7
3-1393223-1 (Alias Part Numbers: "V23061B1007X 82")	1-1393223-7 (Alias Part Numbers: "V23061B1007A301")
3-1393223-1 (Alias Part Numbers: "V23061B1007X 82")	6-1416200-7
2-1393223-8 (Alias Part Numbers: "T75S5D112-24" "V23061B1007X 8")	1-1393223-7 (Alias Part Numbers: "V23061B1007A301")
2-1393223-8 (Alias Part Numbers: "T75S5D112-24" "V23061B1007X 8")	6-1416200-7
2-1393223-6 (Alias Part Numbers: "V23061B1007A601")	2-1393225-9 (Alias Part Numbers: "RY612024")

Product Affected**Recommended Replacement**

2-1393223-1

(Alias Part Numbers:
"V23061B1007A401")

1-1393223-7

(Alias Part Numbers:
"V23061B1007A301")

2-1393223-1

(Alias Part Numbers:
"V23061B1007A401")

6-1416200-7

1-1393223-6

(Alias Part Numbers:
"T75S5D112-18"
"V23061B1006X 7")

1-1393223-1

(Alias Part Numbers:
"V23061B1006A301"
)

1-1393223-2

(Alias Part Numbers:
"V23061B1006A401")

1-1393223-1

(Alias Part Numbers:
"V23061B1006A301")

1393223-6

(Alias Part Numbers:
"V23061B1005X 81")

6-1416200-6

1393223-6

(Alias Part Numbers:
"V23061B1005X 81")

9-1393222-1

(Alias Part Numbers:
"V23061B1005A301")

1393223-3

(Alias Part Numbers:
"T75S5D112-12"
"V23061B1005X 6")

6-1416200-6

1393223-3

(Alias Part Numbers:
"T75S5D112-12"
"V23061B1005X 6")

9-1393222-1

(Alias Part Numbers:
"V23061B1005A301"
)

9-1393222-9

(Alias Part Numbers:
"V23061B1005A601")

2-1393225-6

(Alias Part Numbers:
"RY612012")

9-1393222-5

6-1416200-6

Product Affected (Alias Part Numbers: "V23061B1005A401 *X060")	Recommended Replacement
9-1393222-5 (Alias Part Numbers: "V23061B1005A401 *X060")	9-1393222-1 (Alias Part Numbers: "V23061B1005A301")
9-1393222-4 (Alias Part Numbers: "V23061B1005A401")	6-1416200-6
9-1393222-4 (Alias Part Numbers: "V23061B1005A401")	9-1393222-1 (Alias Part Numbers: "V23061B1005A301")
8-1393222-6 (Alias Part Numbers: "V23061B1004A401")	4-1416200-8 (Alias Part Numbers: "V23061B1004A301")
8-1393222-6 (Alias Part Numbers: "V23061B1004A401")	6-1416200-5
7-1393222-9 (Alias Part Numbers: "V23061B1003A401")	3-1416200-8 (Alias Part Numbers: "V23061B1003A301")
7-1393222-9 (Alias Part Numbers: "V23061B1003A401")	6-1416200-4
7-1393222-6 (Alias Part Numbers: "T75S5D112-05" "V23061B1002X 3")	6-1416200-3
7-1393222-6 (Alias Part Numbers: "T75S5D112-05" "V23061B1002X 3")	7-1393222-2 (Alias Part Numbers: "V23061B1002A301")

Product Affected	Recommended Replacement
7-1393222-3 (Alias Part Numbers: "V23061B1002A401")	6-1416200-3
7-1393222-3 (Alias Part Numbers: "V23061B1002A401")	7-1393222-2 (Alias Part Numbers: "V23061B1002A301")
5-1393222-6 (Alias Part Numbers: "V23061A1009A402")	1-1416200-0 (Alias Part Numbers: "V23061A1009A302")
5-1393222-6 (Alias Part Numbers: "V23061A1009A402")	6-1416200-0
4-1393222-8 (Alias Part Numbers: "T75S1D112-24" "V23061A1007X 7")	3-1393222-9 (Alias Part Numbers: "V23061A1007A302")
4-1393222-8 (Alias Part Numbers: "T75S1D112-24" "V23061A1007X 7")	5-1416200-8
4-1393222-7 (Alias Part Numbers: "V23061A1007A602")	1-1393224-8 (Alias Part Numbers: "RYA32024")
4-1393222-2 (Alias Part Numbers: "V23061A1007A402")	3-1393222-9 (Alias Part Numbers: "V23061A1007A302")
4-1393222-2 (Alias Part Numbers: "V23061A1007A402")	5-1416200-8
3-1393222-5	3-1393222-4

Product Affected
(Alias Part Numbers:
"V23061A1006A402")

Recommended Replacement
(Alias Part Numbers:
"V23061A1006A302")

2-1393222-9
(Alias Part Numbers:
"T75S1D112-12"
"V23061A1005X 5")

2-1393222-0
(Alias Part Numbers:
"V23061A1005A302"
)

2-1393222-9
(Alias Part Numbers:
"T75S1D112-12"
"V23061A1005X 5")

5-1416200-0
(Alias Part Numbers:
"V23061C2005A802"
)

2-1393222-3
(Alias Part Numbers:
"V23061A1005A402"
"CA1475-000"
"AMPS-2-1393222-3")

2-1393222-0
(Alias Part Numbers:
"V23061A1005A302"
)

2-1393222-3
(Alias Part Numbers:
"V23061A1005A402"
"CA1475-000"
"AMPS-2-1393222-3")

5-1416200-0
(Alias Part Numbers:
"V23061C2005A802"
)

1-1393222-6
(Alias Part Numbers:
"V23061A1004A402")

1-1393222-5
(Alias Part Numbers:
"V23061A1004A302")

1-1393222-6
(Alias Part Numbers:
"V23061A1004A402")

5-1416200-6

1-1393222-2
(Alias Part Numbers:
"V23061A1003A402")

1393222-9
(Alias Part Numbers:
"V23061A1003A302")

1-1393222-2
(Alias Part Numbers:
"V23061A1003A402")

5-1416200-5

Product Affected

Recommended Replacement

1393222-7
(Alias Part Numbers:
"T75S1D112-05"
"V23061A1002X 2")

1393222-4
(Alias Part Numbers:
"V23061A1002A302"
)

1393222-7
(Alias Part Numbers:
"T75S1D112-05"
"V23061A1002X 2")

5-1416200-4

1393222-5
(Alias Part Numbers:
"V23061A1002A402")

1393222-4
(Alias Part Numbers:
"V23061A1002A302")

1393222-5
(Alias Part Numbers:
"V23061A1002A402")

5-1416200-4

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.