

PCN N° 2017-057A

Introduction of an additional tester platform Advantest V93K
affecting TLE986x and TLE987x



Sales name	SP number	OPN	Package
TLE9861QXA20	SP001095844	TLE9861QXA20XUMA1	PG-VQFN-48
TLE9861QXA20	SP001583362	TLE9861QXA20XUMA2	PG-VQFN-48
TLE9867QXA20	SP000977818	TLE9867QXA20XUMA1	PG-VQFN-48
TLE9867QXA20	SP001583368	TLE9867QXA20XUMA2	PG-VQFN-48
TLE9867QXA40	SP001187214	TLE9867QXA40XUMA1	PG-VQFN-48
TLE9867QXA40	SP001583374	TLE9867QXA40XUMA2	PG-VQFN-48
TLE9867QXW20	SP001380954	TLE9867QXW20XUMA1	PG-VQFN-48
TLE9869QXA20	SP000977814	TLE9869QXA20XUMA1	PG-VQFN-48
TLE9869QXA20	SP001583382	TLE9869QXA20XUMA2	PG-VQFN-48
TLE9871QXA20	SP001119760	TLE9871QXA20XUMA1	PG-VQFN-48
TLE9871QXA20	SP001583398	TLE9871QXA20XUMA2	PG-VQFN-48
TLE9873QXW40	SP001380956	TLE9873QXW40XUMA1	PG-VQFN-48
TLE9877QXA20	SP000977810	TLE9877QXA20XUMA1	PG-VQFN-48
TLE9877QXA20	SP001583420	TLE9877QXA20XUMA2	PG-VQFN-48
TLE9877QXA40	SP001129584	TLE9877QXA40XUMA1	PG-VQFN-48
TLE9877QXA40	SP001583424	TLE9877QXA40XUMA2	PG-VQFN-48
TLE9877QXW40	SP001380958	TLE9877QXW40XUMA1	PG-VQFN-48
TLE9879-2QXA40	SP001611352	TLE98792QXA40XUMA1	PG-VQFN-48
TLE9879QXA20	SP000977808	TLE9879QXA20XUMA1	PG-VQFN-48
TLE9879QXA20	SP001583428	TLE9879QXA20XUMA2	PG-VQFN-48
TLE9879QXA40	SP001129586	TLE9879QXA40XUMA1	PG-VQFN-48
TLE9879QXA40	SP001129586	TLE9879QXA40XUMA1	PG-VQFN-48
TLE9879QXA40	SP001583434	TLE9879QXA40XUMA2	PG-VQFN-48
TLE9879QXW40	SP001380960	TLE9879QXW40XUMA1	PG-VQFN-48