



DOCUMENT TITLE:  
**Product Change Notification – Industrial CF Card Housing Change**

DEPT: Engineering	DOCUMENT NO.	412-0031-00	
PRINT DATE: 12/4/2018	REV	A	Page 1 of 3

**Title of Change:** Industrial CompactFlash Housing Change      **Date:** 11/30/18  
**PCN No:** 412-0031-00

**PCN Effective Date:** 12/14/18<sup>Note1</sup>      **Last Time Buy Date:** N/A  
**Last Time Ship Date:** N/A

**Type of Change:**  
CompactFlash housing change

**Description of Change:**  
Change from sonic welded housing to a press-fit housing.

**Reason for Change:**  
The sonic welded housing supplier has discontinued production, necessitating the move to a press-fit housing. The press-fit housing is already used on high capacity ruggedized cards and retail cards, therefore all Delkin CompactFlash products will utilize the same press-fit housing.


**Products Affected:**  
C300, C400, C500 and C670 Series Industrial CompactFlash card products as shown in attached part number list. Note that some part numbers included in the list may have previously been announced as end of life.

**Impact of Change / Recommended Actions:**  
Delkin expects there to be no impact, as the press-fit housing is a form, fit and functional replacement for the sonic welded housing, meeting all dimensional requirements of the CFA standard, as well as passing all standard environmental testing.

However, if a sample is needed, please contact your Delkin Devices Account Manager to make arrangements.

**Reference Documents/Attachments:**  
Affected part number list attached.

Note 1: The effectivity date of 12/17/18 is estimated, based on CF card order rate and when the remaining inventory of sonic welded housings is projected to be consumed. There will be some amount of finished goods inventory with the sonic welded housing at the time this transition occurs. Therefore, for a period of time, it is possible that shipments could contain cards with both types of housings.

Sincerely,  
  
Tina Guidotti  
Director of Product Management and Technical Support  
Delkin Devices, Inc.

**Affected Part Numbers**

<b>Affected Part Number</b>	<b>Affected Part Number</b>	<b>Affected Part Number</b>	<b>Affected Part Number</b>
CA04TFNHP-F2023-D	CE08TFNDV-FD000-D	CE12TFJHK-FD000-D	CE64MGMYR-FD050-D
CA0GTFHHP-F2023-D	CE08TFNDV-XX000-D	CE12TFJHK-X1000-D	CF02TFLHH-F1000-D
CA0GTFHHP-F2108-D	CE08TFNHB-FD000-D	CE12TFJHK-XX000-D	CF02TFLHH-XX000-D
CA0GTFHHP-XX105-D	CE08TFNHB-FD066-D	CE16TFPCW-FD066-D	CF02TFLVB-FD114-D
CA12TFJHP-FD023-D	CE08TFNHNK-F1000-D	CE16TFPDV-FD000-D	CF02TFNHP-F1000-D
CA25TFJHP-FD023-D	CE08TFNHNK-F1050-D	CE16TFPDV-XX000-D	CF02TFNHP-FD000-D
CA25TFKHP-XX119-D	CE08TFNHNK-F2000-D	CE16TFPHB-FD000-D	CF02TFNHP-X1000-D
CA51TFLHP-X1093-D	CE08TFNHNK-FD000-D	CE16TFPHB-FD066-D	CF02TFNHP-XX000-D
CE02MHWCB-FD000-D	CE08TFNHNK-FDB48-D	CE16TFPHK-F1000-D	CF02TFNHP-XX149-D
CE02MHWCB-XX000-D	CE08TFNHNK-XX000-D	CE16TFPHK-FD000-D	CF02TFNHR-F2023-D
CE02MHWCK-FD000-D	CE08TFNHNK-XX050-D	CE16TFPHK-FDA48-D	CF02TFNHR-F2090-D
CE02MHWHS-FD000-5	CE08TFNHNK-XX106-D	CE16TFPHK-FDB48-D	CF02TFNHR-F2125-D
CE02MHWHS-XX000-5	CE08TFNHQ-X3000-D	CE16TFPHK-XX000-D	CF02TFNHR-F2D23-D
CE02TFHHK-FDB48-D	CE08TFNHQ-XX000-D	CE16TGPCB-FD000-D	CF02TLQAY-X2204-D
CE02TFLHH-FD048-D	CE08TFNVA-FD000-D	CE16TGPCB-FD066-D	CF04MHWHT-FD000-D
CE02TFLHH-FDC48-D	CE08TFPDV-FD000-D	CE16TGPCB-XX000-D	CF04TFNHP-F2000-D
CE02TFLHH-XX000-D	CE08TFPDV-FD060-D	CE16TGPVR-FD000-D	CF04TFNHP-FD000-D
CE02TFND2-FD082-D	CE08TFPHB-FD000-D	CE16TGPVR-FD144-D	CF04TFNHP-XX000-D
CE02TFNDV-F1000-D	CE08TFPHB-FD060-D	CE25MJBHS-F1000-5	CF04TFNHR-F2023-D
CE02TFNDV-F2000-D	CE08TFPHK-F1000-D	CE25MJBHS-FD000-5	CF04TGPAY-X2204-D
CE02TFNDV-FD000-D	CE08TFPHK-F2000-D	CE25MJBHS-X1000-5	CF06MJBAY-X2204-D
CE02TFNDV-X1000-D	CE08TFPHK-FD000-D	CE25MJBHS-X2000-5	CF06MJBHT-F2000-D
CE02TFNDV-XX000-D	CE08TGPDH-FD082-D	CE25MJBHS-XX000-5	CF06MJBHT-F2023-D
CE02TFNHNK-F1000-D	CE08TLQCB-F1000-D	CE25MJBHS-XX119-5	CF06MJBHT-F2126-D
CE02TFNHNK-F2000-D	CE08TLQCB-FD000-D	CE25TFJHK-FD048-D	CF08TFNHP-FD000-D
CE02TFNHNK-FD000-D	CE08TLQCB-FD066-D	CE25TFKHH-FD048-D	CF08TFNHP-XX000-D
CE02TFNHNK-FD050-D	CE08TLQCB-X1000-D	CE25TFKHH-X1000-D	CF08TFPHP-F1000-D
CE02TFNHNK-X1000-D	CE08TLQCB-X3000-D	CE25TFKHH-XX000-D	CF08TFPHP-FD000-D
CE02TFNHNK-XX000-D	CE08TLQCB-XX000-D	CE25TFKHK-F1000-D	CF08TFPHP-X1000-D
CE02TFNHNK-XX050-D	CE08TLQVR-FD000-D	CE25TFKHK-F2000-D	CF0GTFHAY-X2204-D
CE02TLQCC-F2023-D	CE08TLQVR-FD050-D	CE25TFKHK-FD000-D	CF0GTFHHP-F1000-D
CE02TLQCC-F2D23-D	CE08TLQVR-FD137-D	CE25TFKHK-FD161-D	CF0GTFHHP-FD000-D
CE02TLQCK-FD000-D	CE08TLQVR-X3000-D	CE25TFKHK-X1000-D	CF0GTFHHP-X1000-D
CE02TLQDH-FD082-D	CE08TLQVR-XX000-D	CE25TFKHK-X2000-D	CF0GTFHHP-XX000-D
CE02TMCCB-FD000-D	CE0GMHWCW-FD082-5	CE25TFKHK-XX000-D	CF0GTFHHR-F2023-D
CE02TQHDH-FD082-D	CE0GMHWHS-F1000-5	CE25TFKHK-XX010-D	CF0GTFLHP-F1000-D
CE04MHWCB-FD000-D	CE0GMHWHS-FD000-5	CE25TFKHK-XX161-D	CF0GTFLHP-FD000-D
CE04MHWHS-F1000-5	CE0GMHWHS-X1000-5	CE32MGGAJ-FD000-D	CF12MJBAY-X2204-D
CE04MHWHS-FD000-5	CE0GMHWHS-XX000-5	CE32MGGCB-FD000-D	CF12TFJHH-FD000-D

Affected Part Number	Affected Part Number	Affected Part Number	Affected Part Number
CE04MHWHS-FD191-5	CE0GTFHDV-FD000-D	CE32MGGCB-FD048-D	CF12TFJHH-X1000-D
CE04MHWHS-X1000-5	CE0GTFHDV-X1000-D	CE32MGGVR-FD050-D	CF12TFJHH-XX000-D
CE04MHWHS-X2000-5	CE0GTFHHH-FD000-D	CE32MGGYR-FD000-D	CF12TFJHP-FD000-D
CE04MHWHS-XX000-5	CE0GTFHHK-F1000-D	CE32MGGYR-X2000-D	CF12TFJHP-FD008-D
CE04TFNDV-F2000-D	CE0GTFHHK-FD000-D	CE32MGGYR-XX000-D	CF12TFJHP-X1000-D
CE04TFNDV-FD000-D	CE0GTFHHK-FD038-D	CE32NKBYR-FD000-D	CF12TFJHP-XX000-D
CE04TFNDV-X1000-D	CE0GTFHHK-FDA03-D	CE32NKBYR-FD048-D	CF12TFJHR-F2023-D
CE04TFNDV-XX000-D	CE0GTFHHK-X1000-D	CE51MHVHS-FD000-5	CF16TFPHB-XX000-D
CE04TFNHK-F2000-D	CE0GTFHHK-XX000-D	CE51MJBHS-FD000-5	CF16TFPHP-FD000-D
CE04TFNHK-FD000-D	CE0GTFHHK-XX038-D	CE51MJBHS-XX000-5	CF16TFPHP-X1000-D
CE04TFNHK-FD050-D	CE0GTFHHK-XX050-D	CE51TFJHH-FD048-D	CF16TFPHP-XX000-D
CE04TFNHK-FDB48-D	CE0GTFHHQ-FD106-D	CE51TFKHK-FD048-D	CF25TFJHR-F2023-D
CE04TFNHK-FDD48-D	CE0GTFLHH-F1000-D	CE51TFLCW-FD082-D	CF25TFKAY-X2204-D
CE04TFNHK-X1000-D	CE0GTFLHH-F1048-D	CE51TFLD2-FD082-D	CF25TFKHH-F1000-D
CE04TFNHK-XX000-D	CE0GTFLHH-FD000-D	CE51TFLD2-FD128-D	CF25TFKHH-XX000-D
CE04TFNHK-XX050-D	CE0GTFLHH-FD048-D	CE51TFLDH-FD082-D	CF25TFKHP-F1000-D
CE04TFNHK-XX162-D	CE0GTFLHH-X1000-D	CE51TFLHH-F1000-D	CF25TFKHP-FD000-D
CE04TFPHK-F2000-D	CE0GTFLHH-XX000-D	CE51TFLHH-FD000-D	CF25TFKHP-X1000-D
CE04TFPHK-FD000-D	CE0GTFLHK-F1000-D	CE51TFLHH-FD048-D	CF25TFKHP-XX000-D
CE04TLRCB-XX000-D	CE0GTFLHK-FD000-D	CE51TFLHH-X1000-D	CF25TFKHP-XX119-D
CE04TMCCB-FD000-D	CE0GTFLHK-FDB48-D	CE51TFLHH-XX000-D	CF25TFKHR-F2023-D
CE04TMCCB-X1000-D	CE0GTMCCB-FD000-D	CE51TFLHH-XX048-D	CF51TFLAY-X2204-D
CE04TMCCB-X1194-D	CE12MJBHS-F1000-5	CE51TFLHK-F1000-D	CF51TFLHH-F1000-D
CE04TMCCB-XX000-D	CE12MJBHS-F1118-5	CE51TFLHK-FD000-D	CF51TFLHH-FD000-D
CE04TMCVR-FD000-D	CE12MJBHS-FD000-5	CE51TFLHK-FD073-D	CF51TFLHH-XX000-D
CE04TMCVR-X1000-D	CE12MJBHS-FD000-D	CE51TFLHK-FD082-D	CF51TFLHP-F1000-D
CE06TFMHK-F1000-D	CE12MJBHS-X1000-5	CE51TFLHK-FD128-D	CF51TFLHP-FD000-D
CE06TFMHK-FD000-D	CE12MJBHS-XX000-5	CE51TFLHK-X1000-D	CF51TFLHP-FD122-D
CE06TFMHK-X1100-D	CE12TFJD2-XX000-D	CE51TFLHK-X2000-D	CF51TFLHP-X1000-D
CE06TFMHK-X1110-D	CE12TFJHH-FD048-D	CE51TFLHK-XX050-D	CF51TFLHP-XX000-D
CE06TFMHK-X2000-D	CE12TFJHH-X1000-D	CE51TQMDH-FD082-D	CF51TFLHR-F2023-D
CE06TFMHK-X2049-D	CE12TFJHH-XX000-D	CE64MGMCB-F2000-D	CR0GMHWDV-X1000-5
CE08TFND2-FD082-D	CE12TFJHK-F1000-D	CE64MGMYR-FD000-D	CR0GMHWHS-X1000-5
CE0GTFHCW-FD082-D	CE12TFJHK-F2000-D	CE64MGMYR-FD000-D	CR25MJBHS-FD106-5

Note: Some part numbers included in this list may have previously been designated as end of life.