



22-Sep-2017

PCN #:E-17-014011

Subject:HTS heavy duty products

Description of Change: The following part numbers are being obsoleted (obsolete status). A last time buy opportunity is provided as per the dates stated thereafter. Please note that new conditions may apply, please contact your local customer sales representative for a quotation

Reason: Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.

Impact of Change:form - fit - function

Key Dates:

Last Order Date:22-Dec-2017

Last Ship/EOL Date:22-Jan-2018

Product Affected

Recommended Replacement

2-1102611-5

6-1106057-4

3-1102702-5

1-1103341-1

9-1106053-1

2-1102658-5

1103146-1

4-1105101-0

1-1102579-1

(Alias Part Numbers:

"220192-000"

Product Affected
"HTSS-110257911")

Recommended Replacement

2-1103338-6

2-1103350-1

1102700-4

3-1102718-5

1-1102582-1

1103154-1

1103273-1

1103270-1

1-1106301-9

(Alias Part Numbers:

"CE0590-000"

"AMPS-1-1106301-9")

1103061-2

4-1102727-5

1-1103074-2

1103464-1

1-1102664-5

1-1103639-8

1102768-1

1-1103074-3

1-1103351-1

3-1106002-9

1-1103319-1

1103127-1

1102702-1

1-1103349-1

1103116-1

1-1103360-6

1103480-1

1-1103336-1

1-1102585-2

1102840-3

5-1102604-5

1103271-1

2-1102654-5

1-1103302-6

1103074-1

Product Affected**Recommended Replacement**

1-1106317-9

3-1102728-5

5-1106002-9

6-1106002-9

1103352-1

2-1102608-5

1-1102570-1

1102996-1

1103147-1

1-1106057-4

1-1104453-5

1103073-3

5-1106062-6

3-1102761-5

4-1106200-5

(Alias Part Numbers:

"295056-000"

"HTSS-110620045")

1-1102572-7

1-1103074-1

1106032-6

1102789-1

1102894-1

4-1102725-5

3-1102755-5

7-1106053-1

1-1102572-6

2-1103341-6

1-1106209-1

1-1103358-2

(Alias Part Numbers:

"CE0674-000"

"AMPS-1-1103358-2")

1-1103345-2

1102688-1

1-1103364-6

2-1106002-9

1102983-1

Product Affected**Recommended Replacement**

2-1105251-3

1-1103074-4

1-1102601-5

1103415-4

1-1103338-7

(Alias Part Numbers:

"CE0670-000"

"AMPS-1-1103338-7")

1-1103331-1

9-1103501-1

2-1102571-7

1103033-1

1-1103355-1

1102760-1

9-1103500-1

3-1105101-0

1102840-1

1-1103337-6

1103097-1

3-1106200-5

1-1103308-1

1-1103338-6

(Alias Part Numbers:

"CE0679-000"

"AMPS-1-1103338-6")

9-1103500-2

3-1102720-5

6-1102611-5

1106350-1

(Alias Part Numbers:

"830620-000"

"HTSS-110635001")

8-1106053-1

1-1102570-7

(Alias Part Numbers:

"CE0655-000"

"AMPS-1-1102570-7")

Product Affected

Recommended Replacement

2-1103344-6
2-1103346-1
1102839-2
1102693-1
4-1102753-5
1-1103352-1
1103272-1
1102706-1
3-1102734-5
1102736-1
6-1106066-8
1106057-4
1-1103338-1
1103343-1
1102769-1
9-1103501-2
1103430-3
4-1102726-5
7-1102572-6
1-1103341-6
4-1106003-9
4-1102704-5
1-1102569-6
1-1103336-6
1103062-2
3-1106301-9
2-1102570-7
1-1103308-6
1-1106207-2
1-1103640-2
1-1102584-1
2-1103614-3
1102667-3
6-1106050-1
1103061-1
2-1103417-7
1102791-2
1-1102617-5
1-1103350-1

Product Affected
(Alias Part Numbers:
"CE0681-000"
"AMPS-1-1103350-1")

Recommended Replacement

1-1104459-5
1103062-1
7-1106058-5
1-1102600-5
1103061-3
1-1103352-2
1103083-1
1102656-1
4-1102722-5
9-1103344-6
1-1102584-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.