

## **Product Change Notification (PCN)**

PCN Number

506834

Date Issued

April 01, 2019

Reason for Change

Change to Product

Change Type Description

This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.

Reason for Short Notice

**Corrective Actions** 

Assessment of Change

Test report/Specification Test Report

Internal Molex Qualification Date

February 15, 2019

Sample Availability Date (Changed Part)

February 15, 2019

Planned Implementation Date

April 29, 2019

Method of Identifying Change

Product made after planned implementation date can contain the change

#### Before Change

 The eyelets and metal LC adapter housing will be changed to prevent the eyelet from spinning. Shown below is the current design and the new design.





Current Design

New Design

#### After Change

#### Overview

- The circular eyelets used on the metal LC adapters can rotate when the
  mounting screw is installed multiple times. The design of the eyelets will be
  changed from a completely circular shape to a semi-circular shape with
  flats to prevent the eyelet from rotating.
- Product Impact
  - Design changes to both the eyelet and the metal LC adapter housing
- Part Number Impact
  - See attached impacted parts list.
- Qualification Reports and samples available upon request after the date shown above



### **Product Change Notification (PCN)**

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:506834" in the e-mail Subject line for faster response.

# RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com