



Date of issue April 18, 2019

**Subject: Discontinuation Notice of [CCL-CRS10 Series](#)**

We are writing to inform you that Lumex has exhausted all options intended to allow production to resume. Equipment repairs were NOT successful, so we must inform you Lumex cannot support requirements for this series. Therefore, Lumex decided to discontinue the following part numbers from our product offering:

Discontinue following parts immediately :

**[CCL-CRS10A+G](#)**  
**[CCL-CRS10G](#)**  
**[CCL-CRS10GG](#)**  
**[CCL-CRS10H](#)**  
**[CCL-CRS10R](#)**  
**[CCL-CRS10R/G](#)**  
**[CCL-CRS10R/Y](#)**  
**[CCL-CRS10RR](#)**  
**[CCL-CRS10SA](#)**  
**[CCL-CRS10SG](#)**  
**[CCL-CRS10SR](#)**  
**[CCL-CRS10SR/G](#)**  
**[CCL-CRS10SY](#)**  
**[CCL-CRS10UPG](#)**  
**[CCL-CRS10USB](#)**  
**[CCL-CRS10USB-A](#)**  
**[CCL-CRS10Y](#)**  
**[CCL-CRS10Y/G](#)**  
**[CCL-CRS10YY](#)**

There is no direct replacement for this product. The closest recommendation is the SML-LX2832 series. Please contact Lumex Technical Specialists for customer support to transition any customers you might have to a new product.

If you have any questions, feel free to contact your Lumex representative for more information.

(END of the EOL)

Best Regards,

Lumex Product Management Team