

Light is OSRAM


## Not For New Designs OS-NFND-2018-008

17-Dec-2018

**Expected discontinuation date:** 1-5 Years

**Reason:** The following products have reached their end of life.

**OSRAM OS Expectations:** Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products.  
Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Not for new design products

Recommended Replacement

Not for new design products		Recommended Replacement			
Device	Brand	Device	Brand	Datasheet Ordering Code	Expected PDN start
<b>LY B6SP</b>	Power SIDELED	<b>KY DMLN31.FY</b>	SYNIOS P2720	Q65111A6199	Q4 2023
<b>KW CULNM1.TG</b>	OSLON Boost	<b>no replacement</b>			
<b>LCB CRBP</b>	OSLON Signal	<b>LB CRBP</b>	OSLON Signal	Q65112A6186	Q2 2019
<b>LY CKBP</b>	OSLON Signal	<b>LCY CLBP</b>	OSLON Signal	Q65112A3583	Q2 2019