



02-Jul-2019

PCN #:E-19-010302

Subject:Superseding of RP-4800 -SP & -STK Finished Goods parts migrating from Menlo Park, USA, to Trutnov, CZ. UOM Change.

Description of Change: The following part numbers are being superseded (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application.

Reason: Discontinuance. Superseding of RP-4800 -SP & - STK parts. Manufacturing location change for RP-4800 products. You are receiving this notice as TE has record of you purchasing this part on the list below. TE is continuing to move production of RP-4800 Tubing to Trutnov CZ. This on-going transfer is being made in phases until all appropriate equipment has moved. Different parts will move in different phases, consequently all new part numbers may not be immediately available at the end of the notification period. We will start to ship RP-4800 products from CZ after Sept 6th 2019. After this date TE reserves the right to provide qualified products from any of the manufacturing locations during this transfer until the final closure date of Menlo Park by the end of 2019. Not all part numbers will transfer at the same time. Customers may still receive Products from Menlo Park after this transfer date due to inventory. Please Note: The UOM for -SP parts will be M, the UOM for -STK will be PC.

Key Dates:

Last Order Date:06-Sep-2019

Last Ship/EOL Date:31-Dec-2019

Product Affected

EM7161-000

(Alias Part Numbers:

"RP-4800-NO.8-3-SP")

Recommended Replacement

NB29104001

Product Affected	Recommended Replacement
BM9780-000	NB17354001
CR0174-000	NB17334001
CN2133-000	NB17292001
748922-000	NB25004001
(Alias Part Numbers: "1-1199184-8" "RP-4800-NO.3-9-SP")	
5028214001	NB17434001
(Alias Part Numbers: "9-1193783-6" "RP-4800-NO.5-0-SP")	
5027714001	NB17324001
(Alias Part Numbers: "2-1193782-5" "RP-4800-NO.11-0-SP")	
5027712004	NB17342001
(Alias Part Numbers: "2-1193782-3" "RP-4800-NO.11-0-STK")	
5027544003	NB17384001
(Alias Part Numbers: "8-1193781-3" "RP-4800-NO.2-9-SP")	
5027534002	NB24814001
(Alias Part Numbers: "7-1193781-8" "RP-4800-NO.1-9-SP")	
5023224004	NB17474001
(Alias Part Numbers: "1193770-8" "RP-4800-NO.8-0-SP")	
5023222001	NB17482001

Product Affected (Alias Part Numbers: "1193770-6" "RP-4800-NO.8-0-STK")	Recommended Replacement
5020204003 (Alias Part Numbers: "1193754-3" "RP-4800-NO.7-0-SP")	NB17464001
5020202002 (Alias Part Numbers: "1193754-2" "RP-4800-NO.7-0-STK")	NB25132001
5020194004 (Alias Part Numbers: "9-1193753-5" "RP-4800-NO.6-0-SP")	NB17444001
5020192003 (Alias Part Numbers: "9-1193753-3" "RP-4800-NO.6-0-STK")	NB17452001
5020114003 (Alias Part Numbers: "8-1193753-7" "RP-4800-NO.9-0-SP")	NB17504001
5020104007 (Alias Part Numbers: "7-1193753-9" "RP-4800-NO.10-0-SP")	NB17264001
5020102005 (Alias Part Numbers: "7-1193753-6" "RP-4800-NO.10-0-STK")	NB17272001
5020054016	NB17414001

Product Affected (Alias Part Numbers: "5-1193753-7" "RP-4800-NO.4-0-SP")	Recommended Replacement
5020052015 (Alias Part Numbers: "5-1193753-1" "RP-4800-NO.4-0-STK")	NB17422001
5020044017 (Alias Part Numbers: "3-1193753-0" "RP-4800-NO.3-0-SP")	NB17394001
5020042016 (Alias Part Numbers: "2-1193753-5" "RP-4800-NO.3-0-STK")	NB17402001
502002M017 (Alias Part Numbers: "1-1193753-5" "RP-4800-NO.2-0-SP-CS5200")	NB24844001
5020024020 (Alias Part Numbers: "1193753-1" "RP-4800-NO.2-0-SP")	NB17364001
5020022019 (Alias Part Numbers: "9-1193752-0" "RP-4800-NO.2-0-STK")	NB17372001
5020014024 (Alias Part Numbers: "6-1193752-4" "RP-4800-NO.1-0-SP")	NB17304001
5020012023	NB17312001

Product Affected

(Alias Part Numbers:

"5-1193752-9"

"RP-4800-NO.1-0-STK")

Recommended Replacement

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.