



TE Connectivity

Product Change Notification: E-19-015065

PCN Date: 30-SEP-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

(AXICOM) FP2 relay - discontinuation of production.

Description of Changes

The following part numbers are being obsoleted (obsolete status). A last time buy opportunity is provided as per the dates stated thereafter. Please note that new conditions may apply, please contact your local customer sales representative for a quotation

Reason for Changes:

Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
01-MAY-2020	
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
30-SEP-2020	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1462033-3	YES		D3006			
1-1462033-4	YES		D3009			
1462033-5	YES		D3002			
2-1462033-1	YES		D3010			
2-1462033-2	YES		D3012			
3-1462033-2	YES		D3021			
3-1462033-4	YES		D3023			
3-1462033-6	YES		D3025			
3-1462033-7	YES		D3026			
3-1462033-8	YES		D3027			
4-1462033-0	YES		D3041			
4-1462033-2	YES		D3043			
4-1462033-5	YES		D3046			
4-1462033-6	YES		D3047			
4-1462033-7	YES		D3061			
4-1462033-9	YES		D3063			
5-1462033-4	YES		480877, D3066			
5-1462033-6	YES		D3067			