



08-Oct-2019

PCN #:E-19-014711

Subject:WinTotal v6 software

Description of Change: The following part numbers are being obsoleted (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application- Drawings are available via TE.com. Part number EC9816-000 superseded by 1-2186545-1 Part number EC9817-000 superseded by 1-2186546-1

Reason: Discontinuance. Product progression and improvement Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter. Part number EC9816-000 superseded by 1-2186545-1 Part number EC9817-000 superseded by 1-2186546-1

Key Dates:

Last Order Date:20-Dec-2019

Last Ship/EOL Date:24-Dec-2019

Product Affected

EC9816-000

(Alias Part Numbers:

"1-1899810-1"

"WINTOTAL-6-DONGLE")

Recommended Replacement

1-2186545-1

EC9817-000

(Alias Part Numbers:

"1-1899810-2")

1-2186546-1

Product Affected

Recommended Replacement

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.