

Issue Date: November 1st, 2019

Dear Valued Customer,

This notice is to inform you of a site change affecting item(s) you have purchased from Littelfuse.

Description of the Change:

- Part numbers attached to this PCN will be changing their site of final assembly and packaging operations from our Piedras Negras Distribution Center to our Muzquiz Manufacturing Site.
- Parts will be produced with equipment and in work cells duplicated from their current ones.

Reason for The Change:

- The operations affected are similar to those already occurring in the new site. This transfer is in line with our continued efforts to consolidate footprints of common manufacturing types, processes, and ownerships.
- Littelfuse is choosing to invest in equipment duplication, as these processes can still be utilized in our Piedras Negras facility by other products in other business units.

Effective Date of the Change:


- Fabrication and installation of equipment is ongoing; first production from our Muzquiz facility will occur in January 2020 (part number demand-dependent).

What You Need to Do:

- There will be no disruption to your supply of finished goods.
- As no finished good part number will exhibit changes in fit, form, function, or fabrication method due to this initiative, no action is required from you.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zacke Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products



Joe Plazyk
Global Product Manager
Littelfuse Commercial Vehicle Products

Items Purchased by Your Company That Are Affected by The Changes:

0813030.XP
0185050.X
0211010.XP
0211015.XP
0211020.XP
0211025.XP
0211030.XP
0813020.XP
0813040.XP
0813050.XP
0CBF010.XP
0CBF015.XP
0CBF020.XP
0CBF025.XP
0CBF030.XP
0CBF035.XPA
0CBF040.XP
0MCB030.X
0MXB020.X
0MXB030.X
155100-1
0185150.XP
0185100.XP
0185120.XP
0UCB030.XP
0ACB030.XP
0185080.X
0FCB020.XP
0UCB025.XP
0UCB020.XP
0185060.X
0UCB020.X
0ACB020.XP
0UCB015.X
0MNB030.X
0UCB025.X
0UCB030.X

0185070.X
0UCB005.X
0MIB030.X
0MNB025.X
0MIB020.X
0UCB010.X
0ACB020.X
0MIB025.X
0MIB015.X
0UCB015.XP
0MIB010.X
0UCB010.XP
0MCB020.X
0MNB020.X
0MNB015.X
0MNB010.X
0MMB015.X
0MMB020.X
0UCB005.XP
0CCB025.XP
0MCB040.X
0CCB025.X
0FCB020.X
0ACB030.X
0BCB030.X-GM
0MIB005.X
0UCB006.XP
0UCB008.XP
0UCB010.XPA
0UCB015.XPA
0UCB020.XPA
0UCB025.XPA
0UCB030.XPA
0FHM0200ZP
02980900Z
02980900TXN
0FHA0030XP

FHAC0002LXN
FHAC0002XP
0FHA0200ZP
0FHM0002XP
03500417XP
0498900.TXN
FHAC0001LXN
0FHA0001XPGLO
FHLM0200ZPA
0FHM0001XPGLO
0FHM0001LXN
FHM20200ZPA
0FHM0001SXJ
0FNXY0030XP
0FHA0002XP
MAHC0001TXJ
FHAC0002SXJ
0FHM0002LXN
0FHA0001XP
0FNXY0020XP
0FNXY0001XP
FHAC0001SXJ
0FHM0001XP
0MAB0001XP
FHAC0001XP
0FHA0002SXJ
03500418XP
01530008LXN
08680062H
0FHA0001LXN
03453LF2XP
0FHA0001SXJ
02980900Z-PAC
04980900S
01500260LXN
0FHM0002SXJ
02980900S

07991001ZXFD
0AFH0002XP
0FHM0003ZXJB-F05
01550400LXN
FHJC1002L
FHJC2002L
0FHM0002X-GM
03500418TXN
0AFH0001XP
0FNXY0002ZXJ-F30
01550300LXN
0FHM0200S
0MAB0001S
0FHM0002X-E-GM
0FHM0002ZXJG-F10
0FNXY0002SXJ-F20