

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|-----------|--------------------|------------------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 01 | 002 | 010 | 0000000513 | 0031.3501 | Circuit Protection | FAS fuse holder | n/a |
| | | | | 0031.3502 | | FAS fuse holder socket | n/a |
| | | | | 0031.3511 | | FAS fuse holder | n/a |
| | | | | 0031.3512 | | FAS fuse holder socket | n/a |
| | | | | 0031.3521 | | FAS fuse holder | n/a |



*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of markings

3 Detailed description of change

Enlarge the markings on the fuse holder.

| Old product appearance | New product appearance |
|--|---|
|  |  |

4 Reason of change

- Better readability of the markings

5 Release date

The change will be rolled-out starting ww 10/2020 (Date code 2010 or higher on label).

6 Impact of change and recommended action

| | | |
|---------------|-----|----------------------------------|
| Form | Yes | No further action recommended |
| Fit | No | No change for dimension |
| Function | No | No change in function |
| Manufacturing | No | No change for manufacturing site |
| Label | No | No change on label |
| Packaging | No | No change in packaging |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|----------------------------|-----------------|
| Data Sheet | FAS fuse holder |

| Product Change Notification | | | | | FAS inscription | | |
|-----------------------------|---------------|--------------|-------------|-----------------|-----------------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-040-167 |
| dislercy | 07.10.2019 | 18.12.2019 | haeckima | 2018490 | A | 1 of 1 | |