

## End of Life Notification

From time to time we find it necessary to change, modify, or replace our product offering. These changes are usually the result of advancements in technology that offer improvements in performance or manufacturability. Unavailability of component parts, generally of an earlier technology or an older design, can cause the obsolescence of outdated product families.

We sincerely appreciate your business and will make every effort to work with you during your transition to the new power supplies. In some cases of obsolescence, a new advanced model has been introduced to replace the existing power supplies. All products now being discontinued are available for an end-of-life last time buy.

We have recommended a suitable replacement for your convenience on most of the end-of-life models. If you have any questions or need specific application assistance, please contact us (you may visit <https://www.artesyn.com/contact>. Email to [productsupport.ep@Artesyn.com](mailto:productsupport.ep@Artesyn.com) or call +1-888-412-7832 - NAM / +44-800-0321546 - EMEA / +86-400-8899-130 - China) or your local sales representative to assist you. Thank you for your continued patronage.

The following series/models have been marked as EOL:

Model No	Product Rank	Replacement Model	Replacement Info	LTB start	LTB end
73-688-0001	E			07/10/2018	01/10/2019
LPS22	L	NPS22-M		12/01/2019	06/30/2020
LPS23	L	NPS23-M		12/01/2019	06/30/2020
LPS24	L	NPS24-M		12/01/2019	06/30/2020
LPS25	L	NPS25-M		12/01/2019	06/30/2020
LPS252-C	L			12/01/2019	06/30/2020
LPS252-CEF	L			12/01/2019	06/30/2020
LPS252-CF	L			12/01/2019	06/30/2020
LPS253-C	L	CPS253-M		12/01/2019	06/30/2020
LPS253-CEF	L			12/01/2019	06/30/2020
LPS253-CF	L			12/01/2019	06/30/2020
LPS254-C	L			12/01/2019	06/30/2020
LPS254-CEF	L			12/01/2019	06/30/2020
LPS254-CF	L			12/01/2019	06/30/2020
LPS255-C	L	CPS255-M		12/01/2019	06/30/2020
LPS255-CEF	L			12/01/2019	06/30/2020
LPS255-CF	L			12/01/2019	06/30/2020

LPT22	L	NPT42-M		12/01/2019	06/30/2020
LPT23	L	NPT43-M		12/01/2019	06/30/2020
LPT24	L	NPT44-M		12/01/2019	06/30/2020
LPT25	L			12/01/2019	06/30/2020
NFS110-7602J	L	LPT104-M		12/01/2019	06/30/2020
NFS110-7602PJ	L	LPT104-M		12/01/2019	06/30/2020
NFS110-7604J	L	LPT103-M		12/01/2019	06/30/2020
NFS110-7604PJ	L	LPT103-M		12/01/2019	06/30/2020
NFS110-7901PJ	L	LPT102-M		12/01/2019	06/30/2020
NFS110-7902PJ	L	LPT104-M		12/01/2019	06/30/2020
NFS110CJ	L			12/01/2019	06/30/2020
NFS40-7605J	L	LPS42		12/01/2019	06/30/2020
NFS40-7607J	L	LPT44		12/01/2019	06/30/2020
NFS40-7608J	L	LPT42		12/01/2019	06/30/2020
NFS40-7610J	L	LPT45		12/01/2019	06/30/2020
NFS40-7612J	L	LPS43		12/01/2019	06/30/2020
NFS40-7615J	L	LPS44		12/01/2019	06/30/2020
NFS40-7624J	L	LPS45		12/01/2019	06/30/2020
NFS40-7628J	L	LPT43		12/01/2019	06/30/2020
NFS40-76S3J	L	LPS41		12/01/2019	06/30/2020
NFS40CJ	L			12/01/2019	06/30/2020
CXA10-48S05J	L	AEE03A36-LS		10/18/2019	04/17/2020
CXA10-48S05-SJ	L	AEE03A36-LS	AEE does not have an enable pin	10/18/2019	04/17/2020
CXA10-48S12J	L	AEE01B36-LS		10/18/2019	04/17/2020
IBC04-36S12-J	L		No replacement available	10/17/2019	12/31/2019
AVE450-48S32LD	L	AVE450B-48S28-6L/M		10/17/2019	12/31/2019
AVO100-36S3V3B-6L	L			10/18/2019	12/31/2019
AVO100-48S1V8-6L	L			10/18/2019	12/31/2019
AVO100-48S1V8B-6L	L			10/18/2019	12/31/2019
AVO100-48S1V8P-6L	L			12/18/2019	12/31/2019
AVO100-48S1V8PB-6L	L			10/18/2019	12/31/2019
AVO100-48S2V5-6L	L			10/18/2019	12/31/2019
AVO100-48S2V5B-6L	L			10/18/2019	12/31/2019
AVO100-48S2V5P-6L	L			10/18/2019	12/31/2019

AVO100-48S2V5PB-6L	L			10/18/2019	12/31/2019
AVO100B-48S1V5-6L	L			10/18/2019	12/31/2019
AVO100B-48S1V5B-6L	L			09/18/2019	12/31/2019
AVO100B-48S1V5P-6L	L			10/18/2019	12/31/2019
AVO100B-48S1V5PB-6L	L			10/18/2019	12/31/2019
ADQ700-48S12B-4LHS	L			10/18/2019	12/31/2019
ADQ700-48S12B-4LIHS	L			10/18/2019	12/31/2019
AVO75B-36S3V3-6L	L			11/06/2019	12/31/2019
AVO75B-36S3V3B-6L	L			11/06/2019	12/31/2019

[Click here to see more EOL information](#)