



Expertise Applied | Answers Delivered

Littelfuse, Inc.  
8755 West Higgins Road, Suite 500  
Chicago, IL 60631 USA  
(773) 628-1000

## Product Discontinuation Notice PDN No.: 41350

**April 28th, 2020**

To: Our Valued Customers,

Littelfuse would like to notify you our decision to obsolete the following parts:

<b>IXYS product type:</b>	<b>Type</b>	<b>Recommended replacement</b>
	MG12100D-BA1MM	MG12100S-BN2MM
	MG12105S-BA1MM	MG12100S-BN2MM
	MG12150D-BA1MM	MG12150S-BN2MM
	MG12200D-BA1MM	MG12200D-BN2MM
	MG12300D-BA1MM	MG12300D-BN2MM
	MG1250S-BA1MM	No replacement
	MG1275S-BA1MM	MG12100S-BN2MM
	MG06100S-BR1MM	No replacement

**Reason:** Die discontinuation

**Last time order date:** Not available

**Internal Reference:** LFPCN#41350

In case of any question, please contact:

Initiator	Title/Function	Date	e-mail
Andreas Laschek-Enders	PM	April 28 <sup>th</sup> , 2020	alaschek-enders@littelfuse.com

IXYS Semiconductor GmbH  
Edisonstr. 15  
D-68623 Lampertheim  
Phone: +49-6206-503-201  
Fax: +49-6206-503-627

### Customer response: (please fill in and return by e-mail, fax or mail within 4 weeks)

for further questions / information    Company: \_\_\_\_\_

    please comment                                  Name & Position: \_\_\_\_\_

  Phone / Fax No.: \_\_\_\_\_

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_