



## Product Change Notification

**Product Category** : [Tools & Production Supplies](#) (MAGNIFIERS)

**Issue Date** : 03/24//2020

**Effective Date** : 03/24//2020

**LTB Date** : N/A

**LTD Date** : N/A

**Reason For Change** : Dialog wants customers to use DA14585/6 and DA14682/3 for new designs because

- These parts have a richer feature set
- They are complying to the BLE 5 standard
- Their SDKs are actively maintained

Therefore the usage of the “older parts” DA14580/1/2/3 and DA14680/1 for new designs needs to be discouraged by means of A not recommended for new design (NRFND) statement for DA14580/1/2/3 and DA14680/1. Actively referring to DA14585/6 and DA14682/3 for new designs. Discontinuing development hardware supply for DA14580/1/2/3 and DA14680/1.

**EOL** : DA14582

**Parts Effected** : Below are the list of parts which are affected.





PART NUMBER	REPLACEMENT PART NUMBER
DA14580-01UN	DA14585-00000VV
DA14580-01AT	DA14585-00000AT
DA14581-00UN	DA14585-00000VV
DA14581-00AT	DA14585-00000AT
DA14581-00000VRA	DA14585-00000VV
DA14582-01KA	None
DA14583-01F01AT	Refer to DA14586-00F02AT
DA14580DEVKT-B	DA14585-00ATDEVKT-B
DA14580DEVKT-P	DA14585-00ATDEVKT-P
DA14580UNDB-P	DA14585-00VVDB-P
DA14580ATDB-P	DA14585-00ATDB-P
DA14581UNDB-P	DA14585-00VVDB-P
DA14581ATDB-P	DA14585-00ATDB-P
DA14583F01ATDB-P	DA14586-00F02ATDB-P
DA14583IOTSENSKT	DA14585IOTMSSENSKT
DA14583SENSDNGL	DA14585IOTMSSENSOR
DA14680-01F08A9	DA14682-00F08A9
DA14681-01000U2	DA14683-00000U2
DA14681-01000A9	DA14683-00000A9
DA14681-01A9DEVKT-B	DA14683-00A9DEVKT-U
DA14681-01A9DEVKT-P	DA14683-00A9DEVKT-P
DA14681-01U2DB-P	DA14683-00U2DB-P
DA14681-01A9DB-P	DA14683-00A9DB-P
HOMEKTADDONDB	None

