

10-Jun-2020 **PCN** #:P-20-019171

Subject:4pos MCON 1.2 - LL Connector, Sealed

Description of Change: Seal and inner hsg design improved for better seal position assurance. Seal profile and perimeter changed for more secure sitting on the inner hsg. Inner hsg sealing groove adopted accordingly. Please consider this as a replacement for an earlier distributed PCN:E-16-009898. This does not represent any additional change to the former one.

Reason: Customer Request.Product Improvement. Engineering proposal.

Key Dates: Contact By Date:01-Sep-2020 Implementation Date:01-Sep-2020

Product Affected

2-1718656-5 3-1718656-5 1-1718645-2 1-2286471-1 1-1718645-1 1-1718656-3 2-2287274-2 2-2287274-3 2-2287274-3 2-2287274-3 2-2287274-1 1-2112802-1 1-2208397-2 2-1718645-1 2-1718656-1 4-1718656-5

Product Affected

1-1718656-5 2-1718656-3 1-2208397-1 2-1718645-2 1-2287274-1 2-1670918-1 1-1670918-1 1-2289319-1 1-1718656-1 3-1718656-1 1-2289107-1 1-1718656-4 2-1718656-4 determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.