

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Removal of label on tube affecting TO packages from legacy IR and packed at all subcon partners

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

INFORMATION NOTE



N° 055/20

Removal of label on tube affecting TO packages from legacy IR and packed at all subcon partners

► Products affected:

Please refer to attached affected product list 1_cip05520



► Detailed Change Information:

Subject: Standardization of legacy IR products with Infineon Technologies (IFX) packing.

- Reason:**
- This change will apply to all IFX subcon partners. However, parts coming from Rectificadores Internacionales, S.A. de C.V., Tijuana , Mexico (IRMX) will continue to have the tube label.
 - This will be implemented in multiple phase as subcon partners implement the change in their manufacturing facilities.
 - During this duration, there will be situation that customers will receive shipments with and without labels as we cannot remove all labels in all existing inventories.

Description:


Old

- Individual tube label



New

- No label will be pasted on tube



► Product Identification:

Identification available on Barcode Product Label (BPL) on outer packing

► Impact of Change:

Infineon does not see any negative impact on quality, function and reliability as it is only standardization of packing.

► Attachments:

Affected product list 1_cip05520.xlsx

► Intended start of delivery:

24-06-2020

Note: Mixture of product with and without label after implementation, depending on inventory.

If you have any questions, please do not hesitate to contact your local Sales office.