

Product Change Notification

End of Life Notification

Product Category : Motor Drivers / Motor Speed Controllers

Issue Date : 07 - 26 - 2020

Effective Date : 07 - 26 - 2020

LTB Date : 06/19/20

LTD Date : 12/30/20

Reason For Change : In an ongoing effort of offer rationalization in conjunction with continued supply chain challenges, Schneider Electric will obsolete the TeSys U Enclosed offer effective immediately.

Part Affected : Below are the list of part which are affected.

| END OF LIFE PART NUMBERS | | | |
|--------------------------|--------------|------------|-------------|
| LE1GBKO55N7 | LE1D40AFE7 | LE1M35U716 | LE1D12P7A09 |
| LE1GBKO55U7 | LE1D40AP7 | LE1M35U721 | LE1D12Q7 |
| LE1GBKS55N7 | LE1D40AQ7 | LE1M35U722 | LE1D12R7 |
| LE1GBKS55U7 | LE1D50AP7 | LE2D09N7 | LE1D18F7 |
| LE1GBTO11N7 | LE1D50AQ7 | LE2D09V7 | LE1D18R7 |
| LE1GBTO11U7 | LE1D65AP7A04 | LE2K065M7 | LE1D18U7 |
| LE1GBTS11N7 | LE1D09M7A13 | LE2K065P7 | LE1D25F7 |
| LE1GBTS11U7 | LE1D09U7 | LE2K065U7 | LE1D25N7 |
| LE2GBKO55N7 | LE1D12P7 | LE2K065V7 | LE1D25P7A05 |
| LE2GBKO55U7 | LE1D12U7 | LE2K095P7 | LE1D25Q7 |
| LE2GBKS55N7 | LE1D12V7 | LE3D09N7 | LE1D25U7 |
| LE2GBKS55U7 | LE1D25P7 | LE3D12N7 | LE1D35B7 |
| LE2GBTO11N7 | LE1M35B706 | LE3D12U7 | LE1D35E7 |
| LE2GBTO11U7 | LE1M35B707 | LE3D18N7 | LE1D35F7 |

| | | | |
|--------------|------------|-------------|--------------|
| LE2GBTS11N7 | LE1M35B708 | LE3D18V7 | LE1D35N7 |
| LE2GBTS11U7 | LE1M35B710 | LE3D35N7 | LE1D35P7 |
| LE3GBTO11N7 | LE1M35B712 | LE4D09N7 | LE1D35Q7 |
| LE3GBTO11U7 | LE1M35B714 | LE4D09P7 | LE1D35U7 |
| LE3GBTO22N7 | LE1M35B716 | LE4D09U7A05 | LE1D35V7 |
| LE3GBTO22U7 | LE1M35B721 | LE4D09V7 | LE2D09B7 |
| LE3GBTS11N7 | LE1M35B722 | LE4D18F7 | LE2D09P7 |
| LE3GBTS11U7 | LE1M35M707 | LE4D18N7 | LE2D12P7 |
| LE3GBTS22N7 | LE1M35M710 | LE4D18R7 | LE2D12V7 |
| LE3GBTS22U7 | LE1M35M721 | LE4D18U7 | LE2D18P7 |
| LE1M35M708 | LE1M35N705 | LE4D35N7 | LE2D25P7 |
| LE1M35M712 | LE1M35N706 | LE8K065P7 | LE3D09P7 |
| LE1M35N708 | LE1M35N707 | LE8K065V7 | LE3D12V7 |
| LE1M35N710 | LE1M35N721 | LE8K095Q7 | LE3D18U7 |
| LE1M35N712 | LE1M35P708 | LE1D09Q7 | LE4D09Q7 |
| LE1M35N714 | LE1M35P712 | LE1D09B7 | LE4D09V7A04 |
| LE1M35N716 | LE1M35P722 | LE1D09F7 | LE4D12V7 |
| LE1M35N722 | LE1M35Q707 | LE1D09FE7 | LE4D35V7 |
| LE1D09M7 | LE1M35Q708 | LE1D09N7A04 | LE6D12V7 |
| LE1D09N7 | LE1M35Q710 | LE1D09P7A04 | LE6D18P7 |
| LE1D12N7 | LE1M35Q712 | LE1D09P7A05 | LE1D18B7 |
| LE1D18N7 | LE1M35Q716 | LE1D09P7A13 | LE1D25B7 |
| LE1M35U708 | LE1M35Q721 | LE1D09P7T | LE1D50AFE7 |
| LE1D18P7A05 | LE1M35R707 | LE1D09R7 | LE3D18P7 |
| LE1GVMEK | LE1M35U705 | LE1D09U7A13 | LE3D35P7 |
| LE4D12F7 | LE1M35U706 | LE1D09V7A05 | LE6D09V7 |
| LE1D25V7 | LE1M35U707 | LE1D09V7A13 | LE3D09V7 |
| LE1D18M7 | LE1M35U710 | LE1D12B7 | LE1D09P7 |
| LE1D09B7A05 | LE1M35U712 | LE1D12F7 | LE1D09V7 |
| LE1D09P7A13T | LE1M35U714 | LE1D12M7 | LE3GBTS11U7. |

