

Light is OSRAM


Not For New Designs OS-NFND-2020-005

17 August 2020

Expected discontinuation date: 1-5 Years

Reason: The following products have reached their end of life.

OSRAM OS Expectations: Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products.
Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Not for new design products		Recommended Replacement			
Device	Brand	Device	Brand	Datasheet Ordering Code	Expected PDN start
LB CRBP	OSLON Signal	LB CRBP.01	OSLON Signal	Q65112A9298	Q4 2021
LCB CRBP	OSLON Signal	LB CRBP.01	OSLON Signal	Q65112A9298	Q4 2021
LCY CLBP	OSLON Signal	LCY CRBP.01	OSLON Signal	Q65112A9297	Q4 2021
LJ CKBP	OSLON Signal	LJ CRBP.01	OSLON Signal	Q65112A9260	Q4 2021
LT CQBP	OSLON Signal	LT CRBP.01	OSLON Signal	Q65112A9257	15. December 2020
LUW CRBP	OSLON Signal	LUW CRBP.01	OSLON Signal	Q65112A9296	Q4 2021
LV CQBP	OSLON Signal	LV CRBP.01	OSLON Signal	Q65112A9258	15. December 2020