

Product Change Notice

Issue Date: 8. September 2020

Change Type:

Ink mark to laser mark.

Parts Affected:

BCM53202MIPBG
BCM53202MKPBG
BCM53212MIPBG
BCM53242MKPBG
BCM53242SKPBG
BCM53262MIPBG
BCM53262MKPBG
BCM53262SKPBG

Description and Extent of Change:

BCM532x2 series change from ink mark to laser mark due to ASESH phase out ink mark process

Reasons for Change:

Ink mark process being phased out

Effect of Change on Fit, Form, Function, Quality, or Reliability:

No change in product dimensions, form, function, quality or reliability.

Effective Date of Change:

7 December 2020

Qualification Data:

Not applicable.

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.