Panasonic



Not Recommended for New Design: DS2 Series Relays

NRFND.PG 000 1.10.9 .20 20 10.9 .20 20

About T his Notice:	The DS2 Series Felays are Not Recommended For New Design due to future plans for discontinuation.
Features:	
Effective Date :	Immediate
Affected Parts and/or Replacements :	See Attached. Includes all custom products . There are no direct replacements.
Datasheet(s):	See Attached.
Notes:	DS1 Series Felays are not included in this Notice and remain active .

Panasonic NRFND.PG0001.10.9.2020 DS2 Series Relays

Part Number

DS2E-S-DC3V

DS2E-S-DC5V

DS2E-S-DC6V

DS2E-S-DC9V

DS2E-S-DC12V

DS2E-S-DC24V

DS2E-S-DC48V

DS2E-SL2-DC3V

DS2E-SL2-DC5V

DS2E-SL2-DC6V

DS2E-SL2-DC9V

DS2E-SL2-DC3V

DS2E-SL2-DC24V

D32E-3L2-DC24V

DS2E-SL2-DC48V

DS2Y-S-DC1.5V

DS2Y-S-DC3V

DS2Y-S-DC5V

DS2Y-S-DC6V

DS2Y-S-DC9V

DS2Y-S-DC12V

DS2Y-S-DC24V

DS2Y-S-DC24V-H350

DS2Y-S-DC48V