

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M001020

DATE: 15-Dec-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DG406CJ+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1077LZ-50+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1077U-66+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1077Z-133+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1087LU-466+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1091LU-66+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1091LUB-033+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1099U-PR+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1110E-300+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1110S-350+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1233M-5+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	DS1248W-120+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1248W-120IND+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1706LEUA+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	DS1707EUA+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	DS1817-5+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	ICL7137CQH+D	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	ICL7612ACSA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	ICL7641ECWE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX11129ATI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1142BCAP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1145BCAP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1187BCUI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1203AEPP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1248AEPE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1249AEPE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured

Discontinuance	MAX1295ACEI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX13086EEPD+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX14526DEEWP+	N/A	15-Mar-2021	13-Jun-2021	•
	MAX14526DEEWF+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance					Part can no longer be manufactured
Discontinuance	MAX14719EWC+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1495CCJ+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1497EPI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX15013DASA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX15048ETJ+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX1508YETA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX154BEAG+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1567ETL+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX157AEPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX16001CTE+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX16032ETM+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX16039PLA23+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX165BCPN+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX17005BETP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX17005BETP+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX170CEPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX174AEPI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX188ACAP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX188CCAP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX189BCPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1963AEZT100+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX199ACWI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX2663EUT+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX2663EUT+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX3070EAPD+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX3078EAPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX3094EEPE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX3187CAX+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX3355EEBC+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX3480EBCPI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX3486EEPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX394CAP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured

Discontinuance	MAX409BEPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4210AEUA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4211CEUE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4285ESA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4354ESD+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4391CSA+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX4437EUA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4529EUA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX452CPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4535CPD+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4545EWP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4553CEE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4577EUA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4583EPE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4585EUB+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4754AETE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4802ACQI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4811CTN+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4811CTN+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4915AELT+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4915AELT+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5052AEUA+	N/A	15-Jun-2021	15-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX5071CAUA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX508BEPP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5111GTJ+	MAX5112GTJ+	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5150AEEE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5154ACPE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5175BEEE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX518BEPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX520AEAP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX521BEPP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5293EUE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX530AEWG+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX537BCPE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5417PETA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5491SA03200+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured

Discontinuance	MAX562EAI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5900ACETT+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5913AEMH+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5930AEEG+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
					-
Discontinuance	MAX5939BESA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5943BEEE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5955BUEE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6129BEUK50+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6129BEUK50+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6133BASA50+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6167BESA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6167BESA+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6306UK44D2+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6306UK44D3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6306UK44D3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6308UK00D1+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6309UK46D3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6309UK46D3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6310UK46D3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6310UK46D3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX631AEPA+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX633AEPA+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6344SUT+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6344SUT+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6383XR22D3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6383XR22D3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6384XS44D3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6384XS44D3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6386XS31D5+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6400BS29+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6413UK16+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6418UK23+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6418UK23+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6422US22+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6422US22+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6424UK22+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured

Discontinuance	MAX6456UT46S+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6469TA28AD3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6502UKP035+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6502UKP035+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6502UKP075+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6502UKP075+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX664C/D	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX666C/D	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6686AU40L+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6710MUT+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6735KASVD3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6825TUK+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6827MUT+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6827MUT+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6827RUT+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6833HXRD0+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6833HXRD0+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6847KASD3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6847KASD3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6854UK26D3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6854UK26D3+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK26D3L+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK26D3L+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6871ETJ+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX690TCPA+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX696C/D	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX7129CPL+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX7231BFI/D	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX7418CUA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX7426EPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX77829EWN+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX792MESE+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX792SCPE+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX820MESE+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX824LEXK+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX824LEXK+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured

Discontinuance	MAX861CUA+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX8648ETE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8680ETL+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8720EEI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8753ETI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8804ZETA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8804ZETA+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8819BETI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8875EUK27+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX8875EUK27+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX8954EWN+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8954EWN+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX9393ETJ+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX953EPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX974EPE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX981CPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX981EPA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX98356EWL+	MAX98358EWL+	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX9877EWP+TG45	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX9929FABT+TG45	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7533KN+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7537LCWG+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7545AKP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7547KEWG+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7821KEWP+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7824LCWG+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7845JN+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MXD1815XR29+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	VT235AWFQ-ADJ	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	VT500FQ	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured