



# Product Change Notification

Current Date: 24-Nov-2020

## TE Connectivity

Product Change Notification: P-20-020088

PCN Date: 24-NOV-20

Customer: TTI, Inc. ( 1305175 )

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

FTZ scoped parts

### Description of Changes

This SCR is a change of transportation mode required upon customer pick-up. Point of Manufacture and Point of Distribution will not change. These products will now be imported by TE from manufacturing region using bonded transportation and distributed from TE Foreign Trade Zones in El Paso, TX and Ontario, CA, USA (distribution point determined at the part level, unchanged). As these products are consumed by customers outside of the United States, TE requests that these parts be received using a bonded carrier and (1) directly exported from the United States, or (2) transferred to customer bonded warehouse or FTZ prior to export from the United States.

### Reason for Changes:

Product improvement. To prevent being charged a surcharge for tariffs, customers must use bonded carriers to pick up parts, and ship to a FTZ.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	20-MAR-2021
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1418775-1</a>	NO		TYC1-1418775-1				
<a href="#">1-967570-1</a>	NO		TYC1-967570-1				
<a href="#">1-968882-1</a>	NO		TYC1-968882-1				
<a href="#">1241412-1</a>	NO		TYC1241412-1				
<a href="#">1241858-2</a>	NO		TYC1241858-2				
<a href="#">1379118-1</a>	NO		TYC1379118-1				
<a href="#">1394133-1</a>	NO		TYC1394133-1				
<a href="#">1418884-1</a>	NO		TYC1418884-1				
<a href="#">1452503-1</a>	NO		TYC1452503-1				
<a href="#">1534149-1</a>	NO		TYC1534149-1				
<a href="#">1544275-2</a>	NO		TYC1544275-2	"P7010870862"			
<a href="#">1544454-1</a>	NO		TYC1544454-1	"P7010870865"			
<a href="#">1719043-1</a>	NO		TYC1719043-1	"80.370.00"			
<a href="#">174464-1</a>	NO		TYC174464-1				
<a href="#">1823111-1</a>	NO						
<a href="#">185311-1</a>	NO		TYC185311-1				
<a href="#">1897015-2</a>	NO		TYC1897015-2				
<a href="#">2-964292-1</a>	NO		TYC2-964292-1				
<a href="#">2141466-1</a>	NO		TYC2141466-1				
<a href="#">2177018-1</a>	NO		TYC2177018-1				
<a href="#">2177610-3</a>	NO		TYC2177610-3				
<a href="#">2302454-1</a>	NO		TYC2302454-1				
<a href="#">2302454-2</a>	NO						
<a href="#">2309309-3</a>	NO		TYC2309309-3				
<a href="#">2822363-1</a>	NO		TYC2822363-1				
<a href="#">5-962885-5</a>	NO		TYC5-962885-5				
<a href="#">5-963716-1</a>	NO		TYC5-963716-1				
<a href="#">5-968220-1</a>	NO		TYC5-968220-1				
<a href="#">6-928918-1</a>	NO		TYC6-928918-1				
<a href="#">828920-1</a>	NO		TYC828920-1	"820A-36911", "5001141"			
<a href="#">828985-1</a>	NO		TYC828985-1				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">9-1718346-1</a>	NO		TYC9-1718346-1				
<a href="#">927365-1</a>	NO		TYC927365-1	"D58550-000", "AMPS-0-0927365-1"			
<a href="#">936121-1</a>	NO		TYC936121-1				
<a href="#">953382-1</a>	NO		TYC953382-1				
<a href="#">964280-2</a>	NO		TYC964280-2				



# Product Change Notification

Current Date: 24-Nov-2020

## TE Connectivity

Product Change Notification: P-20-020088

PCN Date: 24-NOV-20

Customer: TTI, Inc. ( 3057778 )

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

FTZ scoped parts

### Description of Changes

This SCR is a change of transportation mode required upon customer pick-up. Point of Manufacture and Point of Distribution will not change. These products will now be imported by TE from manufacturing region using bonded transportation and distributed from TE Foreign Trade Zones in El Paso, TX and Ontario, CA, USA (distribution point determined at the part level, unchanged). As these products are consumed by customers outside of the United States, TE requests that these parts be received using a bonded carrier and (1) directly exported from the United States, or (2) transferred to customer bonded warehouse or FTZ prior to export from the United States.

### Reason for Changes:

Product improvement. To prevent being charged a surcharge for tariffs, customers must use bonded carriers to pick up parts, and ship to a FTZ.

### Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

20-MAR-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-967570-1</a>	NO		TYC1-967570-1				
<a href="#">1241412-1</a>	NO		TYC1241412-1				
<a href="#">1394133-1</a>	NO		TYC1394133-1				
<a href="#">1418884-1</a>	NO		TYC1418884-1				
<a href="#">1544275-2</a>	NO		TYC1544275-2	"P7010870862"			
<a href="#">1544454-1</a>	NO		TYC1544454-1	"P7010870865"			
<a href="#">1719043-1</a>	NO		TYC1719043-1	"80.370.00"			
<a href="#">174464-1</a>	NO		TYC174464-1				
<a href="#">1823111-1</a>	NO						
<a href="#">185311-1</a>	NO		TYC185311-1				
<a href="#">1897015-2</a>	NO		TYC1897015-2				
<a href="#">2-964292-1</a>	NO		TYC2-964292-1				
<a href="#">2141466-1</a>	NO		TYC2141466-1				
<a href="#">2177018-1</a>	NO		TYC2177018-1				
<a href="#">2177610-3</a>	NO		TYC2177610-3				
<a href="#">2302454-1</a>	NO		TYC2302454-1				
<a href="#">2302454-2</a>	NO						
<a href="#">2822363-1</a>	NO		TYC2822363-1				
<a href="#">5-962885-5</a>	NO		TYC5-962885-5				
<a href="#">5-963716-1</a>	NO		TYC5-963716-1				
<a href="#">5-968220-1</a>	NO		TYC5-968220-1				
<a href="#">6-928918-1</a>	NO		TYC6-928918-1				
<a href="#">828920-1</a>	NO		TYC828920-1	"820A-36911", "5001141"			
<a href="#">828985-1</a>	NO		TYC828985-1				
<a href="#">9-1718346-1</a>	NO		TYC9-1718346-1				
<a href="#">927365-1</a>	NO		TYC927365-1	"D58550-000", "AMPS-0-0927365-1"			
<a href="#">936121-1</a>	NO		TYC936121-1				
<a href="#">953382-1</a>	NO		TYC953382-1				
<a href="#">964280-2</a>	NO		TYC964280-2				

