



List of affected standard parts:

SH6918F700APEP
SH6918F500BPEP
SH8518F800APEP
SH8518F600BPEP
SH8536F1K0APEP

Best Regards,

Brandon Metzger
Marketing Manager

CC: Kirk Schwiebert
Director of Product Development