



Product Change Notification

Current Date: 22-Feb-2021

TE Connectivity

Product Change Notification: E-21-001601

PCN Date: 21-FEB-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

PLUG ASSY, 0.6mm PITCH CHAMP DOCKING CONNECTOR, 40 POS

Description of Changes

Adjust the bending angle of the 2 side flanges on shell of 2129261-1.

Other attachments:

[Docking 2129261-1 EC](#)

Reason for Changes:

Product Improvement. To improve the solderability performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

09-AUG-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2129261-1	NO						

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
2129261-ASCI (Customer Restricted)	2129261-1		B	
2129261	2129261-1		B	



Product Change Notification

Current Date: 22-Feb-2021

TE Connectivity

Product Change Notification: E-21-001601

PCN Date: 21-FEB-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

PLUG ASSY, 0.6mm PITCH CHAMP DOCKING CONNECTOR, 40 POS

Description of Changes

Adjust the bending angle of the 2 side flanges on shell of 2129261-1.

Other attachments:
[Docking 2129261-1 EC](#)
Reason for Changes:

Product Improvement. To improve the solderability performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

09-AUG-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2129261-1	NO						



Docking Plug 2129261-1 EC



Product Development Engineering
Data and Devices
2021-1-13

EVERY CONNECTION COUNTS




Background

To improve the solderability performance during reflow process, make EC change on the shell of docking 2129261-1.

Such design change does not have effect on product function.


Shell EC




Shell EC change:

The only difference between existing and new is the bending angle of the side flanges.

2129261-1 EC



Existing



New

Assembly change:

The only difference between existing and new is the shell component.

~End~