



23-Mar-2021

PCN #:PCN-21-101273

Subject:RAST5 Tab Header, DIN version

Description of Change: Please be aware of an upcoming feature change to the listed part numbers. Before: 0.45mm +/-0.05 After: 0.35mm +/-0.05 Reference performance test data: see attached

Reason: Header Assembly tab contact tip changed to have better performance about connector mating force

Key Dates:

Contact By Date:28-Mar-2021

Implementation Date:28-Mar-2021

Product Affected	Alias Part Number
------------------	-------------------

1971955-2	
4-1971846-7	
1-1971949-3	
1971896-7	
1-2232024-3	
5-1971896-4	
5-1971845-7	
7-1971845-7	
7-1971845-3	
2232001-5	
9-1971846-5	
4-1971896-3	
2-1971895-2	
4-1971846-6	
5-1971845-4	
1-2232001-3	

Product Affected	Alias Part Number
6-1971846-8	
9-1971845-4	
6-1971845-5	
8-1971846-3	
2-1971845-5	
1-1971846-3	
2298030-4	
9-1971846-6	
2-1971845-3	
1971845-3	
1-1971963-3	
7-1971845-6	
1-1971845-4	
2232009-3	
4-1971895-4	
1-2232001-2	
1971846-5	
3-1971845-5	
6-1971846-3	
6-1971846-5	
4-1971846-3	
1-2232000-2	
1971895-4	
3-2304599-2	
1971845-7	
2-1971846-5	
1971846-6	
7-1971846-2	
8-1971845-7	
1971954-2	
7-2232001-2	
1-2232024-8	
7-1971896-4	
1971895-6	
9-2232001-2	
8-2232000-3	
4-1971846-8	
4-1971846-2	
8-2232001-3	
1-1971896-3	

Product Affected	Alias Part Number
------------------	-------------------

3-1971845-6	
1-2298031-4	
8-1971846-6	
2232008-3	
8-1971845-4	
5-1971895-4	
1971845-5	
2-1971896-3	
4-1971845-2	
2232024-3	
1971896-5	
1-1971845-5	
1-1971946-3	
8-1971846-2	
2232025-3	
2-1971846-4	
1-1971955-3	
5-1971846-2	
6-1971845-8	
1971946-2	
1971947-3	
5-1971846-7	
1971845-8	
2-1971845-4	
5-1971845-3	
3-1971846-7	
4-1971845-5	
4-1971845-3	
1-1971955-8	
1-2232008-3	
3-1971895-2	
5-1971896-2	
7-1971845-4	
3-1971846-8	
3-1971845-3	
7-1971845-5	
1-1971845-8	
3-1971949-3	
1971845-6	
3-1971846-4	

Product Affected	Alias Part Number
7-1971846-5	
1971846-4	
4-1971846-4	
4-1971896-2	
2-1971896-2	
1971895-5	
2-1971846-8	
9-1971845-7	
3-1971896-4	
1-2232009-8	
7-1971846-6	
4-1971957-3	
4-1971845-8	
6-1971846-2	
1971846-3	
8-1971846-5	
2-1971896-4	
9-1971845-3	
1-2232025-8	
1-1971962-3	
9-1971845-5	
6-1971846-4	
1-1971846-5	
1971895-3	
1-1971896-2	
1-2232000-3	
1-1971954-2	
1971946-7	
1-2232009-3	
1-1971963-8	
8-1971845-5	
2-1971845-7	
5-1971846-8	
3-1971948-3	
2-1971845-6	
4-1971896-4	
7-1971845-2	
6-1971895-2	
7-1971846-4	
3-1971895-4	

Product Affected	Alias Part Number
------------------	-------------------

1-1971949-8	
1-1971956-8	
1971846-7	
1-2232025-3	
2-1971846-2	
5-1971845-8	
1-1971947-3	
1-1971895-6	
9-1971846-7	
5-1971845-6	
3-1971896-3	
2232001-2	
1-1971962-8	
2-1971846-6	
8-1971845-2	
2-1971846-7	
2-1971895-3	
3-2232001-2	
1-2232000-8	
1971846-8	
5-1971846-5	
4-1971895-2	
6-1971845-6	
4-1971895-3	
6-1971845-7	
6-1971845-3	
1-1971846-4	
1971895-7	
7-1971846-7	
6-1971896-4	
5-1971895-2	
1971896-4	
3-1971895-3	
1971896-3	
1-1971946-8	
5-1971846-3	
3-1971846-3	
2232001-4	
1-1971896-4	
9-1971846-2	

Product Affected	Alias Part Number
3-1971846-6	
1971954-5	
1-1971845-7	
5-1971846-6	
9-1971845-2	
2-1971846-3	
4-1971845-6	
1-1971846-2	
1-1971956-3	
6-1971896-2	
2-2232001-2	
1-1971846-8	
1-1971948-8	
3-1971846-2	
3-1971896-2	
2232000-2	
1-1971896-6	
9-1971846-4	
8-1971845-3	
1-1971954-3	
3-1971845-4	
1-1971954-8	
8-1971845-6	
1971845-4	
6-1971845-4	
1-1971845-6	
2-1971895-4	
6-1971895-4	
2-1971845-2	
7-1971895-4	
5-1971895-3	
4-1971846-5	
1-1971895-3	
1971896-6	
7-1971846-3	
3-1971845-2	
1971946-3	
1-1971948-3	
1-1971957-8	
8-1971846-4	

Product Affected	Alias Part Number
6-1971846-6	
3-1971846-5	
1-1971895-2	
9-1971846-3	
9-1971895-4	
1-1971895-4	
1-1971845-2	
5-2232001-2	
1-2232008-8	
1971896-2	
1-1971947-8	
9-1971845-6	
3-1971845-8	
1971846-2	
3-1971845-7	
1-2232001-8	
2232906-4	
5-1971845-5	
1-1971846-6	
4-1971845-4	
1-1971845-3	
1971963-3	
6-1971846-7	
1-1971957-3	
1971895-2	
6-1971845-2	
8-1971895-4	
4-1971956-3	
1971845-2	
1-1971895-5	
1-1971846-7	
5-1971845-2	
8-1971846-7	
2-1971845-8	
5-1971846-4	
4-1971845-7	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.