

Product Discontinuance

Document #:PD23933XA Issue Date:08 Apr 2021

Title of Change:	1Q2021 Product Discontinuance Notice - Batch 5 (Standard)	
Last Time Buy Date:	08 Oct 2021	
Last Ship Date:	08 Apr 2022	
Contact information:	Contact your local ON Semiconductor Sales Office or PCN.Support@onsemi.com	
Type of notification:	Customers must notify ON Semiconductor (< <u>PCN.Support@onsemi.com</u> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.	

Description and Purpose:

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, ON Semiconductor is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. ON Semiconductor continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

ON Semiconductor has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, ON Semiconductor has partnered with Rochester Electronics who will carry any remaining device inventory to potentially allow for a continued source after ON Semiconductor has completed its business process

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

2 +1 765 868 5022

USA

Japan:

Isao Usuki (isao.usuki@onsemi.com)

***** +81 3 6880 1771

Japan

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

***** +421 33790 2229

Slovakia

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

*****+852 2689 0209

China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

TEM001799 Rev. C Page 1 of 3



Product Discontinuance

Document #:PD23933XA Issue Date:08 Apr 2021

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the <u>PCN Customized Portal</u>.

Device to be Discontinued	Replacement part	Supplier
LV8310HGR2G	STL6900A	SENTELIC
LC05111C01MTTTG	MC3651, MC3011	Mitsumi
LC05111C02MTTTG	MC3651, MC3011	Mitsumi
LC05111C05MTTTG	MC3651, MC3011	Mitsumi
LC05111C13MTTTG	MC3651, MC3011	Mitsumi
LC05111C14MTTTG	MC3651, MC3011	Mitsumi
LC05111C16MTTTG	MC3651, MC3011	Mitsumi
LC05111C18MTTTG	MC3651, MC3011	Mitsumi
LC05111C21MTTTG	MC3651, MC3011	Mitsumi
LC05111C23MTTTG	MC3651, MC3011	Mitsumi
LC05111C25MTTTG	MC3651, MC3011	Mitsumi
LC05132C01MTTTG	MC3651, MC3011	Mitsumi
LC05711A91RATBG	MC3651, MC3011	Mitsumi
LC05732A03RATBG	MC3651, MC3011	Mitsumi
LC05732A91RATBG	MC3651, MC3011	Mitsumi
LC06511D04MXTAG	MJ3401	Mitsumi
LC06511F3BMXTAG	MJ3401	Mitsumi
LC06511F6BMXTAG	MJ3401	Mitsumi
LC06511F7AMXTAG	MJ3401	Mitsumi
LC06511F9BMXTAG	MJ3401	Mitsumi
LC05711A01RATBG	MC3651, MC3011	Mitsumi
LC05732A01RATBG	MC3651, MC3011	Mitsumi
LV8314CGR2G	#NONE	#NA
LV8316HGR2G	#NONE	#NA
LV8324CGR2G	#NONE	#NA
LV8344CGR2G	#NONE	#NA
LC06514D01MXTAG	MJ3401	Mitsumi
LC06511F9AMXTAG	MJ3401	Mitsumi
LC06511F8BMXTAG	MJ3401	Mitsumi
LC06511F8AMXTAG	MJ3401	Mitsumi
LC06511F7BMXTAG	MJ3401	Mitsumi
LC06511F6AMXTAG	MJ3401	Mitsumi
LC06511F5BMXTAG	MJ3401	Mitsumi

TEM001799 Rev. C Page 2 of 3



Product Discontinuance

Document #:PD23933XA Issue Date:08 Apr 2021

LC06511F5AMXTAG	MJ3401	Mitsumi
LC06511F4BMXTAG	MJ3401	Mitsumi
LC06511F4AMXTAG	MJ3401	Mitsumi
LC06511F3AMXTAG	MJ3401	Mitsumi
LC06511F2BMXTAG	MJ3401	Mitsumi
LC06511F2AMXTAG	MJ3401	Mitsumi
LC06511F1BMXTAG	MJ3401	Mitsumi
LC06511F1AMXTAG	MJ3401	Mitsumi
LC06511F03MXTAG	MJ3401	Mitsumi
LC06511D02MXTAG	MJ3401	Mitsumi
LC06511D01MXTAG	MJ3401	Mitsumi

TEM001799 Rev. C Page 3 of 3