

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	032	0000002347	See list below	Connectors	5001	





*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected							
6182.0033	6182.0056						

2 Type of change

Approval marking ENEC05 replaced by ENEC10

3 Detailed description of change

Old product appearance with ENEC05	New product appearance with ENEC10
	
Old label with ENEC05	New label with ENEC10
	

4 Reason of change

Approval changed

5 Release date

Markings on the product and packaging labels will be changed starting week 30/2021 (Date code 2130 or higher). Rollout will last approximately 12 months depending on the variant.

6 Impact of change and recommended action

Form	Yes	Approval marking ENEC05 replaced by ENEC10
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	Yes	Approval marking ENEC05 replaced by ENEC10
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet 5001	

Product Change Notification					PCN 5001		
owner	creation date	release date	released by	change order no	rev	page	D10-057-581
kesslema	26.04.2021	30.04.2021	muehlema	2021882	A	1 of 1	