



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001037

DATE: 03-Jun-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX2140ETH+	MAX2142GTM/V+	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX2140ETH+D	MAX2142GTM/V+	03-Jun-2022	03-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX30208CLB+CTL	MAX30208CLB+	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX30208CLB+TCTL	MAX30208CLB+T	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX32600-J85A+	N/A	03-Jun-2022	30-Nov-2022	The eval kit is no longer supported
Discontinuance	MAX32600-J85B+	N/A	03-Jun-2022	30-Nov-2022	The eval kit is no longer supported
Discontinuance	MAX32600-P85B+	N/A	03-Jun-2022	30-Nov-2022	The eval kit is no longer supported
Discontinuance	MAX32600-W00+	N/A	03-Jun-2022	30-Nov-2022	The eval kit is no longer supported
Discontinuance	MAX32600-W00+T	N/A	03-Jun-2022	30-Nov-2022	The eval kit is no longer supported
Discontinuance	MAX32600-W85B+	N/A	03-Jun-2022	30-Nov-2022	The eval kit is no longer supported
Discontinuance	MAX9260GCB/V+CPT	N/A	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX9260GCB/V+TCPT	N/A	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX96751GGTN/V+	MAX96751FGTN/V+	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX96751GGTN/V+T	MAX96751FGTN/V+T	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX96751GGTN/VY+	MAX96751FGTN/VY+	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX96751GGTN/VY+T	MAX96751FGTN/VY+T	03-Jun-2022	30-Nov-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-Jul-2021