



Customer Information Notification

202105018I : MPC5746C 1N06M and 1N84S Errata Rev Update

Note: This notice is NXP Company Proprietary.

Issue Date: Jun 04, 2021 **Effective date:** Jul 05, 2021



Here is your personalized notification about a NXP general announcement.
For detailed information we invite you to [view this notification online](#)

Change Category

☐ Wafer Fab Process	☐ Assembly Process	☐ Product Marking	☐ Test Process	☐ Design
☐ Wafer Fab Materials	☐ Assembly Materials	☐ Mechanical Specification	☐ Test Equipment	☒ Errata
☐ Wafer Fab Location	☐ Assembly Location	☐ Packing/Shipping/Labeling	☐ Test Location	☐ Electrical spec./Test coverage
☐ Firmware ☐ Other				

PCN Overview

Description

NXP Semiconductors announces an errata update for the MPC5746C mask set 1N06M from revision 5 to revision 6 and an errata update for mask set 1N84S from revision 2 to revision 3.

The revision history included in the updated document provides a details description of the changes.

Errata update for the MPC5746C mask set 1N06M from revision 5 to revision 6:

- 1) Erratum ERR008951, ERR009030, ERR010141, ERR010327 were removed.
- 2) Erratum ERR010340 was revised.
- 3) Erratum ERR010385, ERR010963, ERR011235, ERR011287, ERR011293, ERR011294, ERR011295, ERR011321, ERR050090, ERR050119, ERR050130, ERR050144, ERR050154, ERR050195, ERR050196, ERR050246, ERR050467, ERR050572 were added.

Errata update for the MPC5746C mask set 1N84S from revision 2 to revision 3:

- 1) Erratum ERR008951, ERR010103, ERR010327, ERR010577 were removed.
- 2) Erratum ERR010340 was revised.
- 3) Erratum ERR010385, ERR010603, ERR010963, ERR011235, ERR011287, ERR011293, ERR011294, ERR011295, ERR011321, ERR050090, ERR050119, ERR050130, ERR050144, ERR050154, ERR050195, ERR050196, ERR050246, ERR050467, ERR050572 were added.

The MPC5746C mask set 1N06M errata revision 6 and mask set 1N84S errata revision 3 are attached to this notification and can be found at:

https://www.nxp.com/products/processors-and-microcontrollers/power-architecture/mpc5xxx-microcontrollers/ultra-reliable-mpc57xx-mcus/ultra-reliable-mcus-for-automotive-and-industrial-control-and-gateway:MPC574xB-C-G?tab=Documentation_Tab

Corresponding ZVEI Delta Qualification Matrix ID: SEM-DS-02.

Reason

The Errata has been updated to provide additional technical clarification on some device features.

Identification of Affected Products

Product identification does not change

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Additional information

Additional documents: [view online](#)

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name NXP Technical Support

Position Technical Support

e-mail address tech.support@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply .

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

