

Document #:PD24446X Issue Date:24 Dec 2021

Title of Change:	Immediate Product Discontinuance for Tower Material
Last Time Buy Date:	24 Dec 2021
Last Ship Date:	24 Dec 2021
Contact information:	Contact your local onsemi Sales Office or Ruben.Lopez@onsemi.com
Type of notification:	Customers must notify onsemi (< <u>PCN.Support@onsemi.com</u> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

Due to the lack of subcon support, material being produced in the Tower fab will be immediately discontinued.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. onsemi continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

onsemi wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:
Tom Siegel (tom.siegel@onsemi.com)

2 +1 765 868 5022

USA

Japan:

Isao Usuki (isao.usuki@onsemi.com)

***** +81 3 6880 1771

Japan

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

***** +421 33790 2229

Slovakia

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

*****+852 2689 0209

China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, onsemi ALLOWS ONE (1) DAY FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER ONE (1) DAY BEYOND THE ANNOUNCEMENT DATE.

TEM001799 Rev. E Page 1 of 4



Document #:PD24446X Issue Date:24 Dec 2021

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the <u>PCN Customized Portal</u>.

Device to be Discontinued	Replacement part	Supplier
DMYTADNFAZ08TNS-TJAA	#NONE	#NA
FDC6306P	#NONE	#NA
FDC6323L	#NONE	#NA
FDC6325L	#NONE	#NA
FDD4141	#NONE	#NA
FDD6630A	#NONE	#NA
FDD6685-G	#NONE	#NA
FDG6320C	#NONE	#NA
FDG6332C-PG	#NONE	#NA
FDN336P	#NONE	#NA
FDN342P	#NONE	#NA
FDN361BN	#NONE	#NA
FDS4141	#NONE	#NA
FDS4435A	#NONE	#NA
FDS4465-G	#NONE	#NA
FDS6680AS	#NONE	#NA
FDS6875	#NONE	#NA
FDS6890A	#NONE	#NA
FDS6910	#NONE	#NA
FDS6911	#NONE	#NA
FDS6975	#NONE	#NA
FDS6990AS	#NONE	#NA
FDS9431A	#NONE	#NA
FDS9933A	#NONE	#NA
FDT439N	#NONE	#NA
FDT457N	#NONE	#NA
FDV301N-F169	#NONE	#NA
FDV303N-F169	#NONE	#NA
NDS351AN	#NONE	#NA
NDT451AN	#NONE	#NA
PCF6294W	#NONE	#NA
SI4532DY	#NONE	#NA
2N7002-F169	2N7002	onsemi

TEM001799 Rev. E Page 2 of 4



Document #:PD24446X Issue Date:24 Dec 2021

9G85-BSS138	BSS138	onsemi
BSS84-G	BSS84	onsemi
BSS123-F169	BSS123	onsemi
BSS123W	#NONE	#NA
BSS138-F169	BSS138	onsemi
FDC2512	#NONE	#NA
FDC2512-P	#NONE	#NA
FDC3512	FDS3512	onsemi
FDC3535	#NONE	#NA
FDC5612	FDC5661N	onsemi
FDD3510H	#NONE	#NA
FDD3680	NTD6414AN	onsemi
FDD5612	NTD20N06	onsemi
FDD5614P	FQD17P06	onsemi
FDD5670	FDD13AN06A0	onsemi
FDD5690	NTD5C688NL, FDD5680	onsemi
FDMC5614P	NTTFS5116PL	onsemi
FDMC5614P-B8	NTTFS5116PL	onsemi
FDN5618P	NTF2955	onsemi
FDN5630	NTR5198NL	onsemi
FDS3580	FDS3572	onsemi
FDS4559	#NONE	#NA
FDS6986AS	#NONE	#NA
FDS6699S	#NONE	#NA
FDMS9600S	#NONE	#NA
FDS6982AS	#NONE	#NA
FDS4897AC	#NONE	#NA
FDS6690AS	#NONE	#NA
FDMS9620S	#NONE	#NA
NDS356AP	#NONE	#NA
PCFA3612D	#NONE	#NA
NDS9407	FDFS2P106A	onsemi
NDS7002A-F169	NDS7002A	onsemi
NDS0610-PG	NDS0610	onsemi
NDS0605-F169	NDS0605	onsemi
NDP7060	FQP85N06, RFP70N06	onsemi
NDB6060L	FQB50N06L, FDB13AN06A0	onsemi

TEM001799 Rev. E Page 3 of 4



Document #:PD24446X Issue Date:24 Dec 2021

MTD3055VL	FQD13N06L	onsemi
MTD3055V	FQD13N06	onsemi
G785-BSS123	BSS123	onsemi
FDS9958	#NONE	#NA
FDS8935	#NONE	#NA
FDS5690-NBBM009A	FDS3572	onsemi
FDS5690	FDS3572	onsemi
FDN5630-G	NTR5198NL	onsemi
FDN5630-B8	NTR5198NL	onsemi
FDN5618P-B8	NTF2955	onsemi
FDMC5614P-L701	NTTFS5116PL	onsemi
FDC5614P-G	FDC5614P	onsemi
FDC5612-G	FDC5661N	onsemi
BSS84-F169	BSS84	onsemi
FDY100PZ-G	#NONE	#NA
FDS4465-PG	#NONE	#NA
FDMA1027PT	#NONE	#NA
FDC6333C-G	#NONE	#NA
FDC638P-P	#NONE	#NA

TEM001799 Rev. E Page 4 of 4