



Product Change Notification (PCN)

PCN Number	509549	Date Issued	November 18, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	October 23, 2020		
Sample Availability Date (Changed Part)	October 23, 2020		
Planned Implementation Date	January 15, 2021		
Method of Identifying Change	No special marking on the product or packaging		

RELEASED

Before Change

document correction : top tape peeling strength

- Correct unit Conversion : 10.2~132.5 gf = 0.1 ~ 1.3N
- Description on the current drawings : 10.2~132.5 gf = 0.1 ~ 0.3N
※ 0.3 N is not matched to 132.5 gf (132.5/9.8≠0.3)

9. トップテープの剥離強度: 0.1~0.3N (10.2~132.5gf)
剥離方向は下向き
PEELING OFF FORCE OF TOP TAPE
PEELING DIRECTION AS SHOWN IN FOLLOWING FIGURE:

BEFORE Drawing No.
5031480000-SD PSD 000, Rev.C



AFTER Drawing No.
5031480000-SD PSD 000, Rev.D

After Change

Summary

- the drawing for 503148series is going to be corrected. 0.3 N is not matched to 132.5 gf, and the specification 10.2~132.5 gf is same as JIS and EIA standard.
- Product Impact
 - No impact to Fit, Form or Function.
 - There is no change as product itself.
- Part Number Impact
 - 503148series



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509549**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com