



17-Feb-2022

**PCN #:** P-22-022192

**Subject :** Spec 55F Wires

**Description of Change :** TE Connectivity is changing the sourcing and grade for PVDF resin used as insulation material for Spec 55F Wires. This change is to an alternate grade with similar performance and characteristics.

**Reason :** Part status change. The technical assessment on alternate PVDF grade has been completed by TE's technical team and the results demonstrate similar properties and performance to the existing PVDF grades. These results are obtained through validation trials of various finished parts using the alternate grade as insulation material. No change to form, fit and function of the finished parts has been observed. Test reports on the wire characteristics can be provided upon request.

**Key Dates :**

**Contact By Date:** 28-Mar-2022

**Implementation Date:** 28-Mar-2022

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
438629-000	"5-1193296-1", "55FB2521-20-FLT2-0CS2858"		
CR1946-000	"55FBB2532-20-FLT3-0CS2858"		
834121-000	"55FA0511-18-7L-CS2635", "4-1196512-5"		
CJ6054-000	"55FA0511-16-7L3CS3240"		

545679-000	"5-1194294-2", "55FB1531-12-7L/7L3/7L6-0"		
675707-000	"55FA0511-22-7L2", "8-1195313-0"		
955183-000	"55FB1521-22-A991-0CS2033", "2-1197395-2"		
CY0484-000	"55FB2534-24-FLT3-0CS3347"		
CW0400-000	"55FA/0514-22-7L"		
CX2719-000	"55FB2511-16-7L-0CS3347"		
202554-000	"1199644-2", "55FA0511-20-7L-CS2979"		
747247-000	"55FB1522-20-FLT2-0CS2669", "4-1195829-6"		
653619-000	"7-1195157-5", "FB-FL-1426-0002"		
346499-000	"4-1192608-6", "55FB1511-20-7L-0CS2494"		
033275-000	"9-1190257-4", "55FB2511-16-7L-0CS2858"		
513559-000	"9-1194034-5", "55FA0514-24-7L6"		
143373-000	"3-1191037-8", "55FB1511-12-7L-0CS2494"		

334343-000	"8-1192525-3", "55FA0524-24-7L/7L6"		
777311K001	"2-1196051-1"		
CJ6052-000	"55FA0511-18-7L6CS3240"		
734242-000	"55FB1511-22-7L-0CS2989", "9-1199969-5"		
562520-000	"55FB2521-20-7L/7L6-0-F871", "7-1200216-7"		
EP0335-000	"55FA0511-22-7L-C2635-L364"		
CR5558-000	"55FB1511-22-7L-0-F871"		
297505-000	"2-1192253-1", "55FA0511-22-7L6"		
707461-000	"55FA0511-12-7L", "8-1195545-9"		
171567-000	"1-1191248-2", "55FB1521-14-FLT2-0CS2494"		
733895-000	"55FB1544-24-FLT4-0CS2661", "7-1195731-3"		
832935-000	"55FB1524-24-7L/7L6-0", "1-1196503-5"		
722043-000	"55FB1534-24-7L/7L3/7L6-0", "4-1195645-9"		
C49003-000	"7-1201770-9", "EPD-RWC-18301"		

125867-000	"1190915-6", "55FB1521- 16-7L/7L6-0"		
792525-000	"55FB1521- 18-FLT2- 0CS2636", "1- 1196137-4"		
CJ6045-000	"55FA0511- 20- 7L5CS3240"		
650849-000	"55FB1512- 12-7L- 0CS2669", "1195139-9"		
CY0486-000	"55FB2544- 24-FLT4- 0CS3347"		
CJ6042-000	"55FA0511- 22- 7L6CS3240"		
973079-000	"55FA0514- 24-7L2", "9- 1197520-7"		
398695-000	"6-1192989- 9", "55FB1511- 14-7L- 0CS2494"		
772193-000	"55FB1532- 16-FLT3- 0CS2669", "9- 1196014-3"		
229451-000	"9-1191686- 1", "EPD37756C- US"		
CZ9280-000	"55FA0511- 16-7L3- CS2635"		
909219-000	"55FB1541- 16-FLT4- 0CS2494", "5- 1197062-8"		
CY0482-000	"55FB2524- 24-FLT2- 0CS3347"		
495971-000	"3-1193709- 5", "55FB1541- 16-FLT4- 0CS2636"		

163567-000	"5-1191180-2", "55FB1521-18-FLT2-0CS2494"		
CA8693-000	"EPD-RWC-19983"		
213901-000	"3-1191545-0", "55FA0511-22-7L-CS2493"		
CR1926-000	"55FBF2512-14-7L-0CS2858"		
725441-000	"55FB1511-22-7L-0CS2636", "2-1195670-3"		
CJ6063-000	"55FA0511-12-7L-CS3240"		
241621-000	"1191775-6", "55FB1541-20-FLT4-0CS2636"		
229814-000	"1-1201295-1", "55FB1511-20-7L-0CS2123"		
CN9345-000	"55FA0511-14-7L-CS2979"		
C50453-000	"9-1201344-8", "55FA0514-26-7L3"		
563955-000	"55FA0514-24-7L-CS2661", "3-1194455-5"		
CX2715-000	"55FB2511-20-7L-0CS3347"		
050051-000	"3-1190383-5", "55FB1522-16-7L/7L6-0"		
669097-000	"55FA0514-24-7L-CS2880", "3-1195268-8"		

794821-000	"55FB1522-22-7L/7L6-0", "9-1196152-8"		
E31484-000	"1-1201567-9", "55FB1532-22-7L/7L3/7L6-0"		
CA5994-000	"55FA0534-24-FLT3CS2979", "1-1899123-2"		
E44270-000	"55FB/1512-22-7L-0"		
868853-000	"55FB1511-22-7L5-0CS2539", "8-1196763-8"		
205933-000	"6-1191492-2", "55FB1521-22-7L/7L6-0"		
CB8133-000	"55FA0521-22-7L/7L6CS2989", "6-1899191-4"		
257761-000	"1191886-6", "55FB2544-24-FLT4-0CS2858"		
CX3043-000	"55FB2554-24-FLT5-0"		
802369-000	"55FB2511-20-7L-0CS2858", "5-1196203-9"		
CJ6046-000	"55FA0511-20-7L6CS3240"		
739287-000	"55FB1522-22-FLT2-0CS2669", "6-1195770-8"		
E95793-000	"55FA0521-18-7L/7L6CS2979", "5-1200149-3"		

612215-000	"55FB1521-16-FLT2-0CS2494", "5-1194840-9"		
771015-000	"55FB1524-24-FLT2-0CS2494", "5-1196006-8"		
071523-000	"9-1190536-0", "55FB2511-14-7L-0CS2858"		
130230-000	"4-1199983-3", "55FB1521-22-FLT2-0CS2989"		
234158-000	"6-1200224-6", "55FB2521-22-7L/7L6-0-F871"		
330719-000	"6-1192498-6", "55FB1521-20-FLT2-0CS2494"		
875126-000	"55FA0511-12-7L-CS2979", "2-1200144-1"		
674305-000	"55FB1541-16-FLT4-0", "9-1195303-1"		
CJ6053-000	"55FA0511-16-7L-CS3240"		
958518-000	"5-1201227-5", "55FA0511-20-7L-CS3007"		
014461-000	"1-1190113-3", "55FA0514-24-7L5"		
CR1928-000	"55FBF2512-16-7L-0CS2858"		

A83952-000	"5-1201219-4", "55FA0524-24-7L/7L6CS3009"		
D94195-000	"55FB1544-24-FLT4-0CS2979", "5-1201047-1"		
790527-000	"55FA0511-12-7L-CS2493", "3-1196123-3"		
E67252-000	"1201227-7", "55FA0514-24-7L-CS3008"		
CM3560-000	"CTC-0041-20-L106"		
CX2746-000	"55FB2531-20-FLT3-0CS3347"		
942892-000	"55FB2511-22-7L-0-F871", "8-1200208-1"		
980747-000	"55FB1511-12-7L-0CS2636", "7-1197578-5"		
056081-000	"3-1190427-6", "55FA0511-22-7L3"		
CR1573-000	"55FB2514-24-7L-0"		
CA6652-000	"55FA0521-22-7L/7L6CS2998"		
851317-000	"3-1196637-4", "EPD24734B-US"		
718384-000	"4-1200566-8", "55FB2511-22-7L-0F871-L079"		
F40659-000	"55FB1514-24-7L-0CS2979", "1-1199646-0"		



CP9020-000	"55FB2521-20-7L/7L6-0"		
302595-000	"1-1192292-2", "55FB1531-22-FLT3-0CS2636"		
398657-000	"4-1192989-5", "55FB1522-16-FLT2-0CS2669"		
992410-000	"55FB1541-22-FLT4-0CS2979", "4-1199643-7"		
432641-000	"8-1193253-5", "55FA0521-16-7L/7L6CS2661"		
CJ6070-000	"55FA0514-24-7L5CS3240"		
CJ6025-000	"55FA/7121-22-F830-9CS2541"		
CJ6064-000	"55FA0511-12-7L3CS3240"		
113319-000	"7-1190826-9", "55FB1511-16-7L-0"		
A44395-000	"55FB1534-24-FLT3-0CS2989", "1200930-9"		
870750-000	"55FB1511-20-7L-0CS2979", "8-1199643-7"		
355385-000	"2-1192668-1", "55FB1521-20-FLT2-0CS2636"		
923025-000	"55FA0514-24-7L3", "2-1197161-2"		

690828-000	"55FA0524-24-7L/7L6CS2979", "4-1199646-6"		
C88350-000	"55FB/1522-20-7L/7L6-0"		
CX2744-000	"55FB2531-22-FLT3-0CS3347"		
CJ6037-000	"55FA0511-22-7L-CS3240"		
235759-000	"1191734-5", "55FB1544-24-FLT4-0CS2636"		
CX2748-000	"55FB2531-18-FLT3-0CS3347"		
983811-000	"55FB2511-22-7L-0CS2858", "7-1197600-8"		
263885-000	"1-1191942-7", "55FA0514-22-7L"		
F33163-000	"55FB/1522-22-7L/7L6-0"		
CX2742-000	"55FB2514-24-7L-0CS3347"		
509651-000	"5-1194006-0", "EPD-MPP-10048"		
978359-000	"55FA0511-22-7L-CS2879", "8-1197558-3"		
F71425-000	"55FA0522-20-7L/7L2-CS1938", "9-1200904-0"		
465411-000	"5-1193489-8", "55FB1531-22-7L/7L3/7L6-0"		

305341-000	"9-1192311-6", "55FB1541-22-FLT4-0CS2661"		
850335-000	"55FB2521-16-FLT2-0CS2858", "3-1196630-2"		
C59763-000	"2-1201375-2", "55FA0542-22-G112CS1938"		
772185-000	"55FA0511-20-7L-CS2661", "8-1196014-9"		
871895-000	"55FB1511-20-7L-0", "1196785-8"		
269490-000	"2-1199922-7", "55FB1524-24-FLT2-0CS2989"		
872737-000	"55FB7067-22-0", "3-1196791-6"		
CJ8068-000	"EPD-MPP-10050CS2979", "6-1899307-6"		
298086-000	"1-1199644-7", "55FA0511-22-7L-CS2979"		
CJ6069-000	"55FA0514-24-7L3CS3240"		
617061-000	"55FB1541-22-FLT4-0", "1-1194877-0"		
997906-000	"55FA0514-24-7L-CS2989", "8-1199921-3"		
CA5993-000	"55FA0531-22-FLT3CS2979", "1-1899123-1"		

289895-000	"1192198-2", "55FB1521- 14-FLT2- 0CS2636"		
063837-000	"8-1190482- 3", "55FA0521- 16-7L/7L6"		
CJ6059-000	"55FA0511- 14-7L- CS3240"		
945201-000	"55FB1511- 20-7L- 0CS2661", "4- 1197315-1"		
681891-000	"55FA0511- 18-7L6", "2- 1195360-7"		
024311-000	"3-1190188- 7", "55FA0514- 24-7L"		
CJ6044-000	"55FA0511- 20- 7L3CS3240"		
692391-000	"55FB1554- 26-FLT5-0", "5-1195435- 3"		
498533-000	"2-1193727- 4", "55FA0511- 20-9"		
ER6484-000	"55FB1511- 14-7L- 0CS3533"		
304531-000	"2-1192306- 7", "55FB1511- 22-7L5-0"		
158049-000	"6-1191141- 1", "55FA0511- 14-7L"		
770633-000	"55FA0511- 16-7L- CS2635", "8- 1196003-0"		
402989-000	"1-1193042- 3", "EPD- RWC-12302"		

752209-000	"55FB1522-12-FLT2-0CS2669", "8-1195864-3"		
271222-000	"6-1200616-7", "55FA0514-24-7L-CS2979"		
840867-000	"3-1196560-4", "EPD-RWC-13089"		
263011-000	"1191936-4", "55FB1511-18-7L-0CS2494"		
857707-000	"55FB1524-24-FLT2-0CS2636", "4-1196684-9"		
D04196-000	"55FA0512-20-7L-CS1938", "7-1200905-5"		
998133-000	"55FB1534-24-FLT3-0CS2494", "1-1197718-5"		
337288-000	"6-1199910-8", "55FA0521-20-7L/7L6CS2998"		
CJ6062-000	"55FA0511-14-7L6CS3240"		
CB7435-000	"55FA0524-24-7L/7L6CS2989", "7-1899186-7"		
803019-000	"55FB1534-24-FLT3-0CS2661", "9-1196207-9"		
538897-000	"1-1194229-2", "55FA0524-24-7L/7L6CS2661"		
667889-000	"55FA0511-18-7L0", "8-1195259-7"		

CJ0922-000	"55FA0514-20-7L"		
CA5935-000	"55FB1511-22-7L-0CS2979", "1-1899123-0"		
111273-000	"5-1190812-2", "55FB1514-24-7L-0"		
024993-000	"5-1190193-3", "55FA0511-20-7L"		
A55368-000	"55FA0521-12-7L/7L6CS2979", "2-1200149-8"		
A82869-000	"55FA0522-22-7L/7L5-CS1938", "4-1200905-2"		
790909-000	"55FB2531-20-FLT3-0CS2858", "2-1196126-4"		
CM7053-000	"55FA0511-18-7L-L032"		
CX2721-000	"55FB2511-14-7L-0CS3347"		
059839-000	"2-1201652-3", "55FA0514-26-7L"		
407538-000	"5-1200280-0", "55FB1511-20-7L-0CS2989"		
244035-000	"3-1191790-0", "55FB1522-10-FLT2-0CS2669"		
338391-000	"1192554-6", "EPD-PFM-10032CS2789"		
CM7052-000	"55FA0511-16-7L-L032"		

CJ6061-000	"55FA0511-14-7L5CS3240"		
C64745-000	"9-1201566-0", "55FB1512-22-7L-0"		
E94750-000	"55FB1521-20-FLT2-0CS2989", "9-1200896-3"		
105013-000	"7-1190767-9", "55FB1521-22-A988-0CS2033"		
A87828-000	"8-1200566-0", "55FB2531-22FLT3-0F871L079"		
E07283-000	"55FB2521-22FLT2-0F871L079", "8-1200565-1"		
CR1944-000	"55FBF7130-24-FLT2-0CS2858"		
CX0302-000			
CR1938-000	"55FBF2522-16-FLT2-0CS2858"		
A75314-000	"8-1199826-8", "EPD36877B-01-US-CS2979"		
255487-000	"2-1191870-6", "55FB1521-22-A992-0CS2033"		
D94120-000	"55FA0511-22-7L-CS2989", "5-1200348-8"		
338435-000	"3-1192554-5", "55FA0511-16-7L"		
CN8905-000	"55FB1541-22-FLT4-0CS2989"		

CB7434-000	"55FA0534-24-FLT3CS2989", "7-1899186-8"		
168610-000	"1200226-7", "55FB2531-22-FLT3-0-F871"		
EK5627-000	"55FB1524-22-7L/7L6-0"		
276409-000	"1192047-8", "55FB1521-20-FLT2-0CS2661"		
073155-000	"7-1190547-7", "55FB1511-22-7L9-0"		
CW0399-000	"55FA/0514-20-7L6"		
CJ6066-000	"55FA0511-12-7L6CS3240"		
407399-000	"4-1193073-9", "55FB1524-26-7L/7L6-0"		
CZ9281-000	"55FA0511-22-7L3CS2635"		
132439-000	"5-1190962-7", "55FB7066-22-0"		
CJ6058-000	"55FA0511-16-7L6CS3240"		
192013-000	"7-1191392-6", "55FB1511-16-7L-0CS2636"		
139653-000	"7-1191012-3", "55FA0511-22-7L-F993"		
322751-000	"1-1192443-3", "55FA0514-24-7L-CS2493"		



903730-000	"6-1201231-5", "55FB1521-22-FLT2-0CS3106"		
A82761-000	"55FB2531-22-7L/7L3/7L6-0", "2-1200072-2"		
575279-000	"55FA0511-18-7L", "6-1194565-2"		
952899-000	"55FB1541-20-FLT4-0CS2494", "8-1197378-4"		
476125-000	"7-1200718-2", "55FA0512-20-7L"		
873199-000	"55FB1521-22-FLT2-0CS2661", "7-1196794-0"		
CR1940-000	"55FBF2522-20-FLT2-0CS2858"		
F80661-000	"55FB1524-24-FLT2-0CS2979", "1-1199646-2"		
CF2873-000	"55FB7110-22-7L9/7L5-0-CS3211"		
E00559-000	"55FA0541-12-FLT4CS2979", "4-1200149-7"		
A45293-000	"55FB1521-22-2/6-0CS2979", "1-1200935-3"		
CX2738-000	"55FB2521-14-FLT2-0CS3347"		
CX2736-000	"55FB2521-16-FLT2-0CS3347"		
919099-000	"5-1197132-7", "EPD-MPP-10050"		

845999-000	"55FB1531-22-FLT3-0CS2494", "2-1196599-8"		
084299-000	"1190623-1", "55FB1514-24-7L-0CS2636"		
602733-000	"9-1194770-0", "EPD-PFM-10032"		
778731-000	"55FB1522-20-7L/7L6-0", "9-1196060-7"		
ER4537-000	"55FB1511-16-7L-0-L005"		
EJ1574-000	"55FB7110-22-7L9/7L5-0"		
609348-000	"55FA0524-24-7L/7L6CS1938", "4-1200974-8"		
931983-000	"55FB1514-24-7L-0CS2661", "7-1197223-7"		
CB2069-000	"EPD-RWC-19948"		
E00507-000	"55FA0511-16-7L-CS2979", "6-1199644-5"		
CW0398-000	"55FA/0514-20-7L"		
C55741-000	"1201345-3", "55FA0514-26-7L9"		
CW7515-000	"55FB7122-26-7L/7L6-0"		
CM7054-000	"55FA0511-20-7L-L032"		
126765-000	"5-1190921-3", "55FB1531-20-FLT3-0CS2494"		

440283-000	"9-1193309-8", "55FA0511-20-7L-CS2493"		
C85180-000	"55FA0524-26-7L/7L0CS1938", "8-1200912-0"		
266015-000	"7-1191963-9", "EPD86168A-US"		
678361-000	"55FB1521-22-FLT2-0CS2033", "9-1195332-3"		
EK5413-000			
F43247-000	"55FB1514-24-7L-0CS2989", "7-1199922-0"		
210285-000	"7-1191523-8", "55FA7026-24-0CS2488"		
087643-000	"7-1190646-9", "55FB1511-16-7L-0CS2494"		
258030-000	"1200072-9", "55FB2511-22-7L-0"		
748779-000	"55FA0511-22-7L-E257", "6-1195840-0"		
C84707-000	"2-1201237-6", "55FB1531-22-FLT3-0CS2989"		
289741-000	"8-1192196-0", "55FA0511-22-7L"		
731399-000	"55FB1514-24-7L-0CS2494", "1-1195714-1"		

338761-000	"1192557-5", "55FB1521- 22-A993- OCS2033"		
366365-000	"7-1192746- 8", "55FB2511- 18-7L- OCS2858"		
CB9341-000	"55FB2531- 16- 7L/7L3/7L6- 0"		
451101-000	"9-1193387- 0", "55FB1512- 16-7L-0"		
C42968-000	"55FB2511- 20-7L-0- F871", "1- 1200229-3"		
EK5415-000	"55FB1521- 16- FT20C2173L 375"		
CJ6060-000	"55FA0511- 14- 7L3CS3240"		
651329-000	"55FB1521- 16-FLT2- OCS2636", "6- 1195142-2"		
CW0402-000	"55FA/0514- 24-7L"		
CJ8066-000	"EPD-MPP- 10048CS2979 ", "6- 1899307-5"		
CX2750-000	"55FB2531- 16-FLT3- OCS3347"		
215845-000	"9-1191558- 6", "55FA0514- 24- 7L3CS2635"		
471363-000	"1193532-1", "55FB1521- 20-7L/7L6-0"		
CR1930-000	"55FBF2512- 18-7L- OCS2858"		

935751-000	"55FA0511-16-7L-CS2493", "4-1197250-0"		
CA8690-000			
CX2734-000	"55FB2521-18-FLT2-0CS3347"		
888721-000	"55FA0511-10-7L", "9-1196913-2"		
CX2752-000	"55FB2531-14-FLT3-0CS3347"		
CJ6040-000	"55FA0511-22-7L3CS3240"		
CJ6071-000	"55FA0514-24-7L6CS3240"		
183751-000	"5-1191334-3", "55FA0511-20-7L-CS2635"		
679872-000	"55FB2521-22-7L/7L6-0", "2-1198299-9"		
116817-000	"1190851-6", "55FB1512-16-7L-0CS2669"		
524743-000	"8-1194121-4", "55FA0554-24-F294"		
ER6490-000	"55FB1514-24-7L-0CS3533"		
A59152-000	"6-1201344-1", "55FA0514-26-7L0"		
984353-000	"55FB1511-22-7L9-0CS2173", "6-1197604-4"		
248173-000	"1-1191820-1", "55FA0514-24-7L-CS2635"		

CW0401-000	"55FA/0514-22-7L6"		
894029-000	"55FB1541-22-FLT4-0CS2494", "2-1196953-6"		
CJ6043-000	"55FA0511-20-7L-CS3240"		
CA8691-000			
CJ4028-000	"55FB7126-22-7L/7L6-0-G171"		
CR1950-000	"55FBF7131-24-FLT3-0CS2858"		
856957-000	"55FB1521-22-FLT2-0CS2636", "9-1196678-8"		
CM7086-000	"55FA0511-14-7L-L032"		
CX2732-000	"55FB2521-20-FLT2-0CS3347"		
184697-000	"1191341-2", "EPD-MPP-10047"		
CJ6068-000	"55FA0514-24-7L-CS3240"		
CR1935-000	"55FBF7129-24-7L-0CS2858"		
577335-000	"55FB2531-22-FLT3-0CS2858", "7-1194579-4"		
A32752-000	"2-1201232-2", "55FB1521-20-FLT2-0CS3106"		
608739-000	"55FB2524-24-FLT2-0CS2858", "7-1194814-1"		
F82469-000	"2-1201391-9", "55FB1511-18-7L-0CS2989"		

CJ6065-000	"55FA0511-12-7L5CS3240"		
179327-000	"6-1191303-8", "55FA0521-20-7L/7L6"		
935401-000	"55FA7081-X-5D", "8-1197247-1"		
CA8692-000	"EPD-RWC-19983CS2979", "8-1899139-8"		
CR1932-000	"55FBF2512-20-7L-0CS2858"		
581479-000	"55FA7097-26-7L", "2-1194607-5"		
330055-000	"3-1192494-0", "55FB1511-18-7L-0"		
132599-000	"6-1190963-3", "55FB1531-20-FLT3-0CS2636"		
A91566-000	"7-1201779-5", "55FB1521-22-FLT2-0CS3151"		
CP9018-000	"55FB2511-20-7L-0"		
936815-000	"55FB1512-22-7L-0CS2669", "5-1197257-0"		
CA8912-000	"55FA0511-20-7L-CS2989", "8-1899139-9"		
CR1934-000	"55FBF2512-22-7L-0CS2858"		
668381-000	"55FA0534-24-7L/7L3/7L6", "1-1195263-2"		

A31350-000	"55FB1544-24-FLT4-0CS2989", "8-1200793-0"		
224773-000	"7-1191655-3", "55FA0511-20-7L-CS2879"		
845395-000	"55FB1521-22-7L/7L6-0F887", "9-1196594-3"		
A22063-000	"7-1201876-7", "55FB7120-24-7L-0"		
062610-000	"5-1200227-4", "55FB2531-20-FLT3-0-F871"		
CX2717-000	"55FB2511-18-7L-0CS3347"		
060761-000	"4-1190460-7", "55FB1511-18-7L-0CS2636"		
422220-000	"3-1199644-3", "55FB1534-24-FLT3-0CS2979"		
CJ6041-000	"55FA0511-22-7L5CS3240"		
613545-000	"55FB1521-22-FLT2-0CS2494", "3-1194850-4"		
CP3771-000	"55FB1512-20-7L-0"		
626645-000	"55FB1521-22-A989-0CS2033", "9-1194962-0"		
238673-000	"5-1191754-9", "55FB1522-12-7L/7L6-0"		



240197-000	"1-1191765-3", "55FA0511-12-7L-CS2635"		
CJ6049-000	"55FA0511-18-7L-CS3240"		
C43976-000	"EPD-MPP-10047CS2979"		
D90400-000	"55FB1521-20-FLT2-0CS2979", "1199646-5"		
767093-000	"1-1195978-5", "EPD36877B-01-US"		
CR1942-000	"55FBF2522-22-FLT2-0CS2858"		
003599-000	"2-1190027-6", "55FB2534-24-FLT3-0CS2858"		
F63324-000	"55FB1544-24-FLT4-0CS3010", "3-1200701-8"		
D77804-000	"6-1202072-7", "55FA0524-24-7L/7L0CS2979"		
272607-000	"4-1192019-1", "55FB1531-16-FLT3-0CS2636"		
A35722-000	"55FB/1532-22-7L/7L3/7L6-0"		
CX0303-000			
450893-000	"3-1193386-8", "EPD-RWC-10477"		
497703-000	"3-1193721-2", "EPD-MPP-10049"		

335688-000	"4-1201876-3", "55FB7122-24-7L/7L6-0"		
469983-000	"1-1193522-1", "55FB1541-22-FLT4-0CS2636"		
918188-000	"5-1201227-3", "55FA0511-16-7L-CS3007"		
393769K001	"1-1192954-8"		
689365K001	"8-1195413-6"		
CX0305-000			
478139-000	"5-1193580-3", "55FA0511-22-7L-CS2661"		
E48471-000	"EPD-MPP-10049CS2979"		
CS1777-000	"55FA0514-26-7L0CS3313"		
F63309-000	"55FA0512-16-7L-CS1938", "8-1200904-9"		
CR1575-000	"55FB2534-24-7L/7L3/7L6-0"		
019292-000	"1199645-5", "55FA0514-24-7L6CS2979"		
497991-000	"3-1193723-8", "55FA0511-22-7L5"		
E27840-000	"5-1201345-5", "55FA0514-26-7L5"		

F73215-000	"EPD24734B-US-CS2979", "4-1199826-9"		
E05770-000	"55FB1521-22-FLT2-0CS2979", "8-1199650-3"		
482727-000	"1-1193613-0", "55FB1511-14-7L-0CS2636"		
564715-000	"55FB2521-22-FLT2-0CS2858", "7-1194460-1"		
284391-000	"2-1192149-8", "55FA0511-22-9"		
CR1948-000	"55FBF2532-22-FLT3-0CS2858"		
318661-000	"5-1192417-0", "CTC-0041-20"		
951167-000	"55FA0511-22-7L0", "6-1197355-6"		
775189-000	"55FB1511-22-7L-0", "1196036-8"		
413119-000	"9-1193114-7", "CTC-0041-22"		
CW1265-000	"55FA0511-20-7L3-CS2635"		
CJ6051-000	"55FA0511-18-7L5CS3240"		
CJ6050-000	"55FA0511-18-7L3CS3240"		
F23278-000	"55FA0521-22-7L/7L6CS3009", "4-1199914-2"		

506087-000	"8-1193926-2", "55FB1534-24-FLT3-0CS2636"		
868355-000	"55FA0524-24-7L/7L0", "2-1196760-9"		
483333-000	"3-1193617-9", "55FB1511-20-7L-0CS2636"		
174979-000	"5-1191272-1", "55FB1511-22-7L-0CS2494"		
CP6975-000	"55FB1541-14-FLT4-0CS2636"		
CW0403-000	"55FA/0514-24-7L6"		
CW5617-000	"55FB1542-22-FLT4-0"		
CX2730-000	"55FB2521-22-FLT2-0CS3347"		
C40178-000	"9-1201344-0", "55FA0514-26-7L2"		
242499-000	"7-1191779-3", "55FB2514-24-7L-0CS2858"		
142539-000	"9-1191031-9", "55FA0511-22-7L-CS2635"		
694311-000	"55FB1511-22-7L5-0CS2173", "6-1195447-5"		
418005K001	"1193150-9"		
585989-000	"55FA0511-18-7L2", "1-1194639-7"		

CJ6056-000	"55FA0511-16-7L5CS3240"		
F31597-000	"9-1201295-6", "55FA0511-20-7L-CS2123"		
226851-000	"4-1191670-7", "55FB1544-24-FLT4-0"		
040949-000	"2-1190313-2", "55FB1511-22-7L9-0CS2539"		
037953-000	"3-1190293-1", "55FB1544-24-FLT4-0CS2494"		
CX2713-000	"55FB2511-22-7L-0CS3347"		
212868-000	"6-1199158-8", "55FB1521-14-7L/7L6-0"		
465723-000	"7-1193491-3", "55FB1524-24-FLT2-0CS2661"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.