

Product Name:	678 - DUBOX receptacles	
	678-5NMF-DX CARD CONNECTOR	
Product Manager:	François PILLET	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Design Change	
Change Description:	Removal of standoffs located on bottom parts of the receptacles.	
Reason for Change:	This change is made to increase robustness of the housings by reducing the risk of deformation at the edge. Improved stability during insertion process.	
Affected Parts:	See list	
Effective Date of Change:	25 March ,2022	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	NA	
Qual/Test Data Attached?	NA	
Samples Availability Date:	09 March ,2022	
Available Alternatives?		
Questions?	<i>Contact your local AICC Representative, or Product Manager</i>	
	<i>François PILLET / Product Manager</i>	
	<i>francois.pillet@amphenol-fci.com</i>	

Note:

Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .