# molex

## **Product Change Notification**


	3		
Date Issued :	March 28, 2022	PCN Number :	511814
Reason for Change :	Packaging Method/Quantity Changing		
Description of Change :	This notification is to inform you about part(s) listed in this notice that will undergo changes for new Delivery unit. No changes will be made to the product as a result of this change.		
Reason for Short Notice :	Corrective Actions		
Assessment of Change :	Dimension analysis		
Planned Implementation Date :	June 03, 2022		
Sample Availability Date:	March 31, 2022		
Internal Molex Qualification Date :	May 13, 2022		
Last date to request Samples by Cust	omer: March 31, 2022		

Before Picture

### **Change Point**


Before:

Single Reel (20,000pcs) in a 1.5" Tall Box.



#### After:

4 Reels (80,000pcs) in a 5" Tall Box.





Molex Confidential Information

Molex, LLC – All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

molex

#### After Picture

### **Overview**

- Delivery Unit Change for the 42001 Strain Relief Terminals
  - Change is part of an improvement program standardizing Delivery Unit values to align with packaging standards and ensure product quality.
  - Reduce repackaging of parts from the standard production packaging.
  - Improve customer service by reducing errors in ordering/delivery
- Part Numbers Impacted
  - See attached list
- Product Impact
  - No change in fit , form or function
  - No change in part production
- Delivery unit change only
  - Level 1 PPAP will be provided upon request
  - Package dimensions to ship 1-reel measures 1.5" without tuck corners for compression strength. The change to the 4-reel carton 5" tall with tuck corners for increased handling

2 © **protection** has Reserved. Unauthorized Reproduction/Distribution is Prohibited.

#### Additional Information:

### **Dimensional Analysis of Packaging**

- Current Packaging is 1 reel (20,000pcs) in Box 85-01-0015
  - Box Dimensions are 24 x 24 x 1.5"
  - Box has a center glue joint which is a weak spot for our terminal design (as shown on slide 1 before photo)
  - Small minor flaps at corners do no allow for compression strength when box is closed allowing corners to crush and potential for reels/product in box to be damaged during shipping and handling.
- New Packaging will be 4 reels (80,000pcs) in Box 85-02-0003
  - Box Dimensions are 24.75 x 24.25 x 4.75"
  - There is no center glue joint to cause a weak spot in the packaging
  - Corners have minor flaps that tuck well and provide the outer corners with additional compression strength during shipping and handling (as shown on slide 1 after photo)

Molex Confidential Information

Molex, LLC — All Rights Reserved, Unauthorized Reproduction/Distribution is Prohibited



You may address inquires regarding this PCN by clicking on the below link mailto:pcn\_coordinator@molex.com?subject=PCN\_Notification:511814 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification: PCN Notification: 511814" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com