

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS 20220426-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: **NA** **EMEA** **LATAM** **AP** May-22

IMPACTED REGIONS: **DISCONTINUATION**

REASON FOR CHANGE: **OTHER**

DESCRIPTION OF CHANGE: (Required)

Panduit's Cat 6A UTP Couplers use an aluminum foil tape applied to the coupler housing to achieve industry leading alien crosstalk performance. Panduit is making a permanent change to the color of the foil tape on all Cat 6A UTP Couplers. The old foil tape was colored similar to the color of the housing. Due to global material shortages Panduit will be providing couplers, independent of housing color, with a silver colored foil tape. This change will take place in Panduit's manufacturing facilities in the next few months and will be a permanent change. This change does not affect fit, form, function, or coupler performance.

See images of the new silver foil tape to the right.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

| SCHEDULE FOR CHANGE | Year (YYYY) | Month (MM) | Day (DD) |
|--------------------------------------|-------------|------------|----------|
| New product sample availability date | | | |
| Old product discontinuation date* | | | |

CUSTOMER SERVICE CONTACTS

| | | | | |
|----------------------|--|--|--|---|
| ASIA PACIFIC | AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com | CHINA: 400-820-1900 CHN-CustomerService@panduit.com | HONG KONG: 800-965768 CHN-CustomerService@panduit.com | |
| | INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com | INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com | JAPAN: +81-3-6863-6000 JPN-CS@panduit.com | |
| | KOREA: 02-2182-7300 KOR-CustomerService@panduit.com | MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com | SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com | |
| | TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com | THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com | | |
| | LATIN AMERICA | BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com | MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customer-service@panduit.com | OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com |
| NORTH AMERICA | USA & CANADA: 1-800-777-3300 cs@panduit.com | EMEA | EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com | |

Colored Foil



New Silver Foil



| IMPACTED PART NUMBER(s) |
|-------------------------|
| CC6X88BL |
| CC6X88IG |
| CC6X88IW |
| CC6X88RD |
| CC6X88YL |
| CC6X88BU |
| CC6X88GR |
| CC6X88OR |