

Customer Information Notification

CN-202208001I

Issue date: 18 Aug 2022

Effective date: 17 Sep 2022

Here's your personalized quality information concerning products our customers and partners purchased from Nexperia.

For more details please contact your respective Nexperia CSR/AM.



Addition of 100us pulse line in SOA on BUK7S1R2-40H

Notification information

Nexperia are updating the SOA graph in BUK7S1R2-40H datasheet to include a 100us pulse line

Why do we issue this notification?

Additional information to SOA

Change Category

Fab Assembl [Process y S Process [Product Marking Mechanical Specification Carrier of the second of the s	[] Test Location [] Test Process [] Test Equipmen t	[] Design [X] Errata [] Electrical spec./Tes
-------------------------------------	--	--	--

Material y t

s Materials coverage

Wafer Assembl

Fab y

Location Location

Identification of affected products

Product Identification does not change

Impact

No impact to the product's functionality anticipated

Data sheet revision

A new datasheet will be issued

Disposition of old products

Not applicable

Additional information

View Change Notification Online

Contact and support

For all Quality Notification content inquiries, please contact your local Nexperia Sales Support Team.

For specific questions on this notice or the products affected please contact our specialist directly: pcn@nexperia.com

In case of distribution, please contact you distribution partner.

About Nexperia B.V.

We at Nexperia are the efficiency semiconductor company. We deliver over 90 billion products a year and as such service thousands of global customers, both directly and through our extensive network of channel partners. We are at the heart of billions of electronic devices in the Automotive, Mobile, Industrial, Consumer, Computing, and Communication Infrastructure segments.

You have received this email because you are a designated contact or subscribed to Nexperia Quality Notifications. Nexperia shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

If you would like to adjust your mailing preferences, please click <u>here</u>.