



Product Change Notification

Current Date: 25-Aug-2022

TE Connectivity

Product Change Notification: P-22-023261

PCN Date: 25-AUG-22

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

RF Connector

Description of Changes

Supersedence. The related discontinued parts will be replaced by another active parts. 1)1408150-1 superseded by 2455002-1; 2) 5225396-1 superseded by 2455003-1; 3) 5225973-4 superseded by 2455004-1; 4) 5413589-5 superseded by 2455005-1; 5) 5413589-8 superseded by 2455006-1; 6) 5415332-1 superseded by 2402670-1; 7) 1055065-1 superseded by 2081367-1; 8)1050762-1 superseded by 2081360-1; 9)1052522-1 superseded by 2081361-1; 10)1052523-1 superseded by 2081361-2 ; 11)1053378-1 superseded by 2081362-1; 12)1053634-1 superseded by 2081890-1; 13)221643-1 superseded by 2081363-1; 14)5447647-1 superseded by 2081364-1 ; 15)5447647-3 superseded by 2081365-1.

Reason for Changes:

Product improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

20-SEP-2022

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1050762-1	NO			"2001-7943-00"			
1052522-1	NO						
1052523-1	NO						
1053378-1	NO						
1053634-1	NO						
1055065-1	NO			"2088-0000-02"			
221643-1	NO						
5225396-1	NO						
5225973-4	NO						



Product Change Notification

Current Date: 25-Aug-2022

TE Connectivity

Product Change Notification: P-22-023261

PCN Date: 25-AUG-22

Customer: TTI Inc. (3164508)

Location: Fort Worth

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

RF Connector

Description of Changes

Supersedence. The related discontinued parts will be replaced by another active parts. 1)1408150-1 superseded by 2455002-1; 2) 5225396-1 superseded by 2455003-1; 3) 5225973-4 superseded by 2455004-1; 4) 5413589-5 superseded by 2455005-1; 5) 5413589-8 superseded by 2455006-1; 6) 5415332-1 superseded by 2402670-1; 7) 1055065-1 superseded by 2081367-1; 8)1050762-1 superseded by 2081360-1; 9)1052522-1 superseded by 2081361-1; 10)1052523-1 superseded by 2081361-2 ; 11)1053378-1 superseded by 2081362-1; 12)1053634-1 superseded by 2081890-1; 13)221643-1 superseded by 2081363-1; 14)5447647-1 superseded by 2081364-1 ; 15)5447647-3 superseded by 2081365-1.

Reason for Changes:

Product improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

20-SEP-2022

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1050762-1	NO			"2001-7943-00"			
1052522-1	NO						
1052523-1	NO						
1053378-1	NO						
1053634-1	NO						
1055065-1	NO			"2088-0000-02"			
221643-1	NO						
5225396-1	NO						
5225973-4	NO						