



<b>Title of Change:</b>	FAN2510XY datasheet correct typo error	
<b>Effective date:</b>	28 Feb 2023	
<b>Contact information:</b>	Contact your local onsemi Sales Office or Wayne.Cheng@onsemi.com	
<b>Type of notification:</b>	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.	
<b>Change Category:</b>	Datasheet Change	
<b>Change Sub-Category(s):</b>	Datasheet/Product Doc change	
<b>Sites Affected:</b>		
<b>onsemi Sites</b>		<b>External Foundry/Subcon Sites</b>
None		None
<b>Description and Purpose:</b>		
This Product Bulletin is to announce a correction on a typo error in the datasheet of FAN251015 / FAN251030 / FAN251040 as shown below:		
	<b>Change from</b>	<b>Change to</b>
<b>P45</b>	IOUT_OC_FAULT_LIMIT	IOUT_AVG_FAULT_LIMIT
<b>List of Affected Standard Parts:</b>		
<b>Note:</b> Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the <u><b>PCN Customized Portal</b></u> .		
FAN251040MNTXG	FAN251030MNTXG	FAN251015MNTXG