



# Product Change Notification

Current Date: 02-Aug-2023

## TE Connectivity

Product Change Notification: P-23-024435

PCN Date: 20-APR-23

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

AMP SUPERSEAL 1.5 SRS 2 POSITIONS PLUG ASS'Y

### Description of Changes

TE Brazil is building a new mold (TPA Component) to current tooling replacement.

### Reason for Changes:

Document clarification. Dear Customer, we hereby inform you about local replacement tooling of AMP SUPERSEAL 1.5 SRS. CONNECTOR SECONDARY LOCK FOR 2W. PLUG HOUSING (282073-1) used to assembly the AMP SUPERSEAL 1.5 SRS 2 POSITIONS PLUG ASS'Y listed to this PCN to better meet customer demands and improve our delivery. TE Brazil Manufacturing location operates under certified quality management system in accordance with standard concerned automotive requirements. A TE internal release test based on relevant part specifications will be executed before delivery. PPAP will be submitted before SOP for all customers which had required

### Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">282080-1</a>	NO		"CM8390-000", "AMP-0-0282080-1", "2-42939-6211", "8202611296", "8202613264"			