

Product Series Involved

30 Series PCB Relays

Type of Change

Major - URGENT

Key Change

Obsoleting old line, re-introduction under new line


Scope

Effective immediately Finder will close off all 30 Series part numbers configured 30.xx.x.xxx.0010.

Finder will progress with replacement numbers under the new line which will be coded 30.xx.x.xxx.0020.


The new line and part number will replace the previous line and version over the next few months. PCN will be updated upon completion of change over.

Product Change Notification



Part Numbers Effected

30.xx.x.xxx.0010



Alternative Numbers

30.xx.x.xxx.0020

Timing

Effective immediately

Questions? Contact us at 770-271-4431 or www.finder-us.com