

**Product Discontinuation
Notice**Issue Date
March 1, 2024**Product Discontinuation**

Limit Switches

**D5A series****Recommended Replacement****No recommended replacement****[Final order entry date]**

The end of February, 2025

[Date of The Last Shipping]

The end of June, 2025

[Product Discontinuation and recommended replacement]

Product discontinuation	Recommended replacement
D5A-1100	No recommended replacement
D5A-1200	No recommended replacement
D5A-2100	No recommended replacement
D5A-2200	No recommended replacement
D5A-3200	No recommended replacement
D5A-3202	No recommended replacement
D5A-3210	No recommended replacement
D5A-3212	No recommended replacement
D5A-3300	No recommended replacement
D5A-3302	No recommended replacement
D5A-3310	No recommended replacement
D5A-5210	No recommended replacement
D5A-5310	No recommended replacement
D5A-7400	No recommended replacement
D5A-7403	No recommended replacement
D5A-7410	No recommended replacement
D5A-7413	No recommended replacement
D5A-8511	No recommended replacement
D5A-8512	No recommended replacement
D5A-8514	No recommended replacement
D5A-8515	No recommended replacement
D5A-9511	No recommended replacement
D5A-9512	No recommended replacement
D5A-9514	No recommended replacement
D5A-9515	No recommended replacement

Specifications and prices in this product news are as of the issue date and are subject to change without notice.
Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.