

Product Change Notification (PCN)

PCN #: 10C-2024

Date: October 9th, 2024

1 Products Affected

Ezurio Part Number	Revision Previous	Current Revision	Description
001-0030	1-0	1-1	2.4GHz mFlexPIFA,100mm Lg Cable
EFA2400A3S-10MH4L	A-A	A-B	2.4GHz mFlexPIFA Antenna MH4L
001-0034	A-A	A-B	Dual-Band mFlexPIFA, 120mm, MHF1
EFA2455A3S-12MH4L	A-A	A-B	ANT 2.4/5.5GHZ mFlexPIFA120MM MHF4L D1.13

2 Description of Changes

- The company name has been officially changed from Laird Connectivity to Ezurio. As a result, all product PCB Silkscreen labeling and packaging that previously displayed the Laird Connectivity logo will now feature the updated Ezurio logo. This change includes, but is not limited to:
 - Product labels
 - Product packaging

3 Reason for Change

- This change is being implemented because the company name has been officially changed from Laird Connectivity to Ezurio.

4 Anticipated Impact of the Change

- Besides change in silkscreen to change the company logo from Laird Connectivity to Ezurio, there are no electrical RF implications for this change. There is no form, fit or functional changes.

5 Method of Identifying the Changed Product


5.1 Product (Antenna Silkscreen)

- Revision can be found on the antenna silkscreen. Only major revisions are printed. Logo change from Laird to Ezurio is a sign of the change.



5.2 Bag Label

- Manufacturing date on the bag label will be October 2024 or later



6 Factory Effectivity Date

From October 2024 onwards, this will be implemented as a running change into our production planning for these antennas.

7 Contact Information

Headquarters Ezurio
50 S Main St., Suite 1100
Akron, OH 44308 USA
Tel: 1(330) 434-7929
Fax: 1(330) 434-7931

Website www.ezurio.com

Sales / Support Contact <https://www.ezurio.com/contact>

Product Change Notices (PCNs) will be distributed at the discretion Ezurio. Occasionally, Ezurio may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.