

## PRODUCT CHANGE NOTIFICATION PCN No: PCN-1070

Issue Date: 10/18/2024

Parts Affected	R50BG2-4-0045	Old Rev.	Е	New Rev.	F
	R50BG2-5-0080	]	Е		F
	R50BG2-F-0160	]	Е		F
	R50RB2-4-0045	]	Е	1	F
	R50RB2-5-0080		Е		F
	R50RB2-F-0160		Е		F
	R50RED-4-0030		A		В
	R50RED-5-0080		Е		F
	R50RED-F-0120		A		В
	R50RED-V-0025		В		С
	R50RG2-4-0045		Е		F
	R50RG2-5-0080		Е		F
	R50RGB-F-0160		Е		F
	R50RGB-4-0045		Е		F
	R50RGB-5-0080		Е		F
	R50RGB-F-0160		Е		F
	R50YLW-4-0030		A		В
	R50YLW-5-0090		A		В
	R50YLW-F-0120		A		В
	R50YLW-V-0025		В		С

## **Change Will Affect:**

This change will affect the product specifications.

## **Description of Change:**

The drawings have been updated with accurate dimensions of the products.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.



## PRODUCT CHANGE NOTIFICATION PCN No: PCN-1070

Issue Date: 10/18/2024

Effective Date of Change: October 18, 2024

**Reason for Change:** Typographical error in the datasheets.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.