

Product Group: SIL/Fri Nov 1, 2024/PIN-SIL-057-2024-REV-0

PIN

The DNA of tech."

Datasheet Revision with Spirito SOA for Commercial MOSFETs (Phase-04)

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

| Americas | Europe | Asia |
|-----------------------------------|--------------------------|--------------------------------------|
| Vishay Siliconix | Vishay Electronic GmbH | Vishay Intertechnology Asia Pte. Ltd |
| 2585 Junction Avenue, | DrFelix-Zandman-Platz 1, | 37A Tampines Street 92, #07-01, |
| - | - | - |
| San Jose, Ca, United States 95134 | Selb, Germany D-95100 | Singapore, Singapore 528886 |
| Phone: +1-408-988-8000 | Phone: +49-9287-71-0 | Phone: +65-6788-6668 |
| Fax: +1-408-567-8942 | Fax: +49-9287-70435 | Fax: +65-6788-0988 |
| - | - | - |

Description of Change: As part of Vishay Siliconix commitment to quality, we would like to extend to you a courtesy advisory notification of the datasheet revision with Spirito SOA (Safe Operating Area) for the commercial MOSFET products, including SIJA22DP, SIR510DP, SIR5607DP, SIR870ADP, and SIR872ADP.

There is no change to the materials used in the manufacture of this part. We hope you find this Datasheet Update Advisory helpful.

This Advisory is for information only and there is no need for a response.

Reason for Change: Datasheet Revision

Expected Influence on Quality/Reliability/Performance: No impact on the quality, reliability, performance, material, and the physical form factor.

Part Numbers/Series/Families Affected: Please see materials list on the succeeding page.

Vishay Brand(S): Vishay Siliconix

Time Schedule:

Start Shipment Date: Mon Nov 4, 2024

Sample Availability: Please contact your regional Vishay Sales office for sample availability as usual.

Product Identification: No change on part number and product marking.

Qualification Data: No qualification processed for the document correction and update.

Issued By: Andrew Tsai, andrew.tsai@vishay.com

© 2021 VISHAY INTERTECHNOLOGY, INC. ALL RIGHTS RESERVED.

THIS DOCUMENT IS SUBJECT TO CHANGE WITHOUT NOTICE. THE PRODUCTS DESCRIBED HEREIN AND THIS DOCUMENT ARE SUBJECT TO SPECIFIC DISCLAIMERS, SET FORTH AT www.vishay.com/doc?91000



Product Information Notification

PIN)

Product Group: SIL/Fri Nov 1, 2024/PIN-SIL-057-2024-REV-0

The DNA of tech."

| SIJA22DP-T1-GE3 | SIR510DP-T1-BE3 | SIR510DP-T1-RE3 | SIR5607DP-T1-RE3 | SIR5607DP-T1-UE3 |
|------------------|------------------|------------------|------------------|------------------|
| SiR870ADP-T1-GE3 | SiR870ADP-T1-RE3 | SiR872ADP-T1-GE3 | SiR872ADP-T1-RE3 | |


© 2021 VISHAY INTERTECHNOLOGY, INC. ALL RIGHTS RESERVED.

THIS DOCUMENT IS SUBJECT TO CHANGE WITHOUT NOTICE. THE PRODUCTS DESCRIBED HEREIN AND THIS DOCUMENT ARE SUBJECT TO SPECIFIC DISCLAIMERS, SET FORTH AT www.vishay.com/doc?91000



EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: There will be no effect on quality, reliability, performance, and the minimum/maximum values in the datasheet.

| Vishay Part Number | Datasheet Revision | |
|--------------------|--------------------|--------|
| | Old | New |
| SIJA22DP-T1-GE3 | Rev. A | Rev. B |




Corporate Headquarters 63 Lincoln Highway, Malvem, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com



EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: There will be no effect on quality, reliability, performance, and the minimum/maximum values in the datasheet.

| Vishay Part Number | Datasheet Revision | |
|------------------------------------|--------------------|--------|
| | Old | New |
| SIR510DP-T1-BE3 SIR510DP-T1-RE3 | Rev. D | Rev. E |

BEFORE (SIR510DP, Rev. D):




Corporate Headquarters 63 Lincoln Highway, Malvern, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com



EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: There will be no effect on quality, reliability, performance, and the minimum/maximum values in the datasheet.

| Vishay Part Number | Datasheet Revision | |
|--------------------|--------------------|--------|
| | Old | New |
| SIR5607DP-T1-RE3 | Rev. B | Rev. C |
| SIR5607DP-T1-UE3 | | |

BEFORE (SIR5607DP, Rev. B):



Vishay Intertechnology, Inc.


Corporate Headquarters 63 Lincoln Highway, Malvem, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com



EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: There will be no effect on quality, reliability, performance, and the minimum/maximum values in the datasheet.

| Vishay Part Number | Datasheet Revision | |
|--------------------|--------------------|--------|
| | Old | New |
| SIR870ADP-T1-GE3 | Rev. B | Rev. C |
| SIR870ADP-T1-RE3 | | |

BEFORE (SIR870ADP, Rev. B):



Vishay Intertechnology, Inc.


Corporate Headquarters 63 Lincoln Highway, Malvern, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com



EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: There will be no effect on quality, reliability, performance, and the minimum/maximum values in the datasheet.

| Vishay Part Number | Datasheet Revision | |
|--------------------|--------------------|--------|
| | Old | New |
| SIR872ADP-T1-GE3 | Rev. A | Rev. B |
| SIR872ADP-T1-RE3 | | |


BEFORE (SIR872ADP, Rev. A):



 V_{DS} - Drain-to-Source Voltage (V) * V_{GS} > minimum V_{GS} at which $R_{DS(on)}$ is specified

AFTER (SIR872ADP, Rev. B):

I_D - Drain Current (A)



Vishay Intertechnology, Inc.

Corporate Headquarters 63 Lincoln Highway, Malvern, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com