



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1081

Issue Date: 2/4/2025

Parts Affected	Old Rev.	New Rev.
PLP5-2-100	N	P
PLP5-2-100 BE	N	P
PLP5-2-100 BE54	N	P
PLP5-2-100 GN	N	P
PLP5-2-100 GN54	N	P
PLP5-2-100 RD	N	P
PLP5-2-100 RD54	N	P
PLP5-2-100 YW	N	P
PLP5-2-100 YW54	N	P
PLP5-2-100-54	N	P
PLP5-2-100-D	N	P
PLP5-2-100-D54	N	P
PLP5-2-100-S	N	P
PLP5-2-100-S54	N	P
PLP5-2-1000	N	P
PLP5-2-1000 BE	N	P
PLP5-2-1000 BK	N	P
PLP5-2-1000 GN	N	P
PLP5-2-1000 GY	N	P
PLP5-2-1000 RD	N	P
PLP5-2-1000 YW	N	P
PLP5-2-1000-54	N	P
PLP5-2-125	N	P
PLP5-2-125 BE	N	P
PLP5-2-125 BE54	N	P
PLP5-2-125 BK	N	P
PLP5-2-125 GN	N	P
PLP5-2-125 GN54	N	P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1081

Issue Date: 2/4/2025

Parts Affected	PLP5-2-125 GY	Old Rev.	N	New Rev.	P
	PLP5-2-125 RD		N		P
	PLP5-2-125 RD54		N		P
	PLP5-2-125 YW		N		P
	PLP5-2-125 YW54		N		P
	PLP5-2-125-54		N		P
	PLP5-2-125-D		N		P
	PLP5-2-125-D54		N		P
	PLP5-2-125-S		N		P
	PLP5-2-125-S54		N		P
	PLP5-2-1250		N		P
	PLP5-2-1250 BE		N		P
	PLP5-2-1250 BK		N		P
	PLP5-2-1250 GN		N		P
	PLP5-2-1250 GY		N		P
	PLP5-2-1250 RD		N		P
	PLP5-2-1250 YW		N		P
	PLP5-2-1250-54		N		P
	PLP5-2-1500		N		P
	PLP5-2-1500 BE		N		P
	PLP5-2-1500 BK		N		P
	PLP5-2-1500 GN		N		P
	PLP5-2-1500 GY		N		P
	PLP5-2-1500 RD		N		P
	PLP5-2-1500 YW		N		P
	PLP5-2-1500-54		N		P
	PLP5-2-1500-D		N		P
	PLP5-2-1500-D54		N		P
	PLP5-2-1500-S		N		P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1081

Issue Date: 2/4/2025

Parts Affected	PLP5-2-1500-S54	Old Rev.	N	New Rev.	P
	PLP5-2-2.5MM BE54		N		P
	PLP5-2-2.5MM GN54		N		P
	PLP5-2-2.5MM RD54		N		P
	PLP5-2-2.5MM YW54		N		P
	PLP5-2-2.5MM-D		N		P
	PLP5-2-2.5MM-D54		N		P
	PLP5-2-2.5MM-S		N		P
	PLP5-2-2.5MM-S54		N		P
	PLP5-2-250		N		P
	PLP5-2-250 BE		N		P
	PLP5-2-250 BK		N		P
	PLP5-2-250 GN		N		P
	PLP5-2-250 GY		N		P
	PLP5-2-250 RD		N		P
	PLP5-2-250 YW		N		P
	PLP5-2-250-54		N		P
	PLP5-2-350		N		P
	PLP5-2-350 BE		N		P
	PLP5-2-350 BK		N		P
	PLP5-2-350 GN		N		P
	PLP5-2-350 GY		N		P
	PLP5-2-350 RD		N		P
	PLP5-2-350 YW		N		P
	PLP5-2-350-54		N		P
	PLP5-2-375		N		P
	PLP5-2-375 BE		N		P
	PLP5-2-375 BK		N		P
	PLP5-2-375 GN		N		P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1081

Issue Date: 2/4/2025

Parts Affected	PLP5-2-375 GY	Old Rev.	N	New Rev.	P
	PLP5-2-375 RD		N		P
	PLP5-2-375 YW		N		P
	PLP5-2-375-54		N		P
	PLP5-2-3MM BE54		N		P
	PLP5-2-3MM GN54		N		P
	PLP5-2-3MM RD54		N		P
	PLP5-2-3MM YW54		N		P
	PLP5-2-3MM-D		N		P
	PLP5-2-3MM-D54		N		P
	PLP5-2-3MM-S		N		P
	PLP5-2-3MM-S54		N		P
	PLP5-2-500		N		P
	PLP5-2-500 BE		N		P
	PLP5-2-500 BK		N		P
	PLP5-2-500 GN		N		P
	PLP5-2-500 GY		N		P
	PLP5-2-500 RD		N		P
	PLP5-2-500 YW		N		P
	PLP5-2-500-54		N		P
	PLP5-2-625		N		P
	PLP5-2-625 BE		N		P
	PLP5-2-625 BK		N		P
	PLP5-2-625 GN		N		P
	PLP5-2-625 GY		N		P
	PLP5-2-625 RD		N		P
	PLP5-2-625 YW		N		P
	PLP5-2-625-54		N		P
	PLP5-2-750		N		P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1081

Issue Date: 2/4/2025

Parts Affected	PLP5-2-750 BE	Old Rev.	N	New Rev.	P
	PLP5-2-750 BK		N		P
	PLP5-2-750 GN		N		P
	PLP5-2-750 GY		N		P
	PLP5-2-750 RD		N		P
	PLP5-2-750 YW		N		P
	PLP5-2-750-54		N		P
	PLP5-250		N		P
	PLP5-250 BE		N		P
	PLP5-250 BK		N		P
	PLP5-250 GN		N		P
	PLP5-250 GY		N		P
	PLP5-250 RD		N		P
	PLP5-250 YW		N		P

Change Will Affect:

This change will affect the product specifications.

Description of Change:

The drawing has been revised to include:

- Tolerances for the light pipe body and ribs. (c.f. drawing)
- An updated recommended dimension for the mounting hole from 0.156 in to 0.154 in (+0.001 / -0.002 in).

Effective Date of Change: February 4, 2025

Reason for Change: Discrepancy in datasheet Information.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122