



PRODUCT CHANGE NOTIFICATION
PCN No: PCN-1081
Issue Date: 2/4/2025 (Updated 2/12/2025)

Parts Affected		Old Rev.		New Rev.	
	PLP5-2-100		N		P
	PLP5-2-100 BE		N		P
	PLP5-2-100 BE54		N		P
	PLP5-2-100 GN		N		P
	PLP5-2-100 GN54		N		P
	PLP5-2-100 RD		N		P
	PLP5-2-100 RD54		N		P
	PLP5-2-100 YW		N		P
	PLP5-2-100 YW54		N		P
	PLP5-2-100-54		N		P
	PLP5-2-100-D		N		P
	PLP5-2-100-D54		N		P
	PLP5-2-100-S		N		P
	PLP5-2-100-S54		N		P
	PLP5-2-1000		N		P
	PLP5-2-1000 BE		N		P
	PLP5-2-1000 BK		N		P
	PLP5-2-1000 GN		N		P
	PLP5-2-1000 GY		N		P
	PLP5-2-1000 RD		N		P
	PLP5-2-1000 YW		N		P
	PLP5-2-1000-54		N		P
	PLP5-2-125		N		P
	PLP5-2-125 BE		N		P
	PLP5-2-125 BE54		N		P
	PLP5-2-125 BK		N		P
	PLP5-2-125 GN		N		P
	PLP5-2-125 GN54		N		P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION
PCN No: PCN-1081
Issue Date: 2/4/2025 (Updated 2/12/2025)

Parts Affected	PLP5-2-125 GY	Old Rev.	N	New Rev.	P
	PLP5-2-125 RD		N		P
	PLP5-2-125 RD54		N		P
	PLP5-2-125 YW		N		P
	PLP5-2-125 YW54		N		P
	PLP5-2-125-54		N		P
	PLP5-2-125-D		N		P
	PLP5-2-125-D54		N		P
	PLP5-2-125-S		N		P
	PLP5-2-125-S54		N		P
	PLP5-2-1250		N		P
	PLP5-2-1250 BE		N		P
	PLP5-2-1250 BK		N		P
	PLP5-2-1250 GN		N		P
	PLP5-2-1250 GY		N		P
	PLP5-2-1250 RD		N		P
	PLP5-2-1250 YW		N		P
	PLP5-2-1250-54		N		P
	PLP5-2-1500		N		P
	PLP5-2-1500 BE		N		P
	PLP5-2-1500 BK		N		P
	PLP5-2-1500 GN		N		P
	PLP5-2-1500 GY		N		P
	PLP5-2-1500 RD		N		P
	PLP5-2-1500 YW		N		P
	PLP5-2-1500-54		N		P
	PLP5-2-1500-D		N		P
	PLP5-2-1500-D54		N		P
	PLP5-2-1500-S		N		P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION
PCN No: PCN-1081
Issue Date: 2/4/2025 (Updated 2/12/2025)

Parts Affected	PLP5-2-1500-S54	Old Rev.	N	New Rev.	P
	PLP5-2-2.5MM BE54		N		P
	PLP5-2-2.5MM GN54		N		P
	PLP5-2-2.5MM RD54		N		P
	PLP5-2-2.5MM YW54		N		P
	PLP5-2-2.5MM-D		N		P
	PLP5-2-2.5MM-D54		N		P
	PLP5-2-2.5MM-S		N		P
	PLP5-2-2.5MM-S54		N		P
	PLP5-2-250		N		P
	PLP5-2-250 BE		N		P
	PLP5-2-250 BK		N		P
	PLP5-2-250 GN		N		P
	PLP5-2-250 GY		N		P
	PLP5-2-250 RD		N		P
	PLP5-2-250 YW		N		P
	PLP5-2-250-54		N		P
	PLP5-2-350		N		P
	PLP5-2-350 BE		N		P
	PLP5-2-350 BK		N		P
	PLP5-2-350 GN		N		P
	PLP5-2-350 GY		N		P
	PLP5-2-350 RD		N		P
	PLP5-2-350 YW		N		P
	PLP5-2-350-54		N		P
	PLP5-2-375		N		P
	PLP5-2-375 BE		N		P
	PLP5-2-375 BK		N		P
	PLP5-2-375 GN		N		P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1081

Issue Date: 2/4/2025 (Updated 2/12/2025)

Parts Affected	PLP5-2-375 GY	Old Rev.	N	New Rev.	P
	PLP5-2-375 RD		N		P
	PLP5-2-375 YW		N		P
	PLP5-2-375-54		N		P
	PLP5-2-3MM BE54		N		P
	PLP5-2-3MM GN54		N		P
	PLP5-2-3MM RD54		N		P
	PLP5-2-3MM YW54		N		P
	PLP5-2-3MM-D		N		P
	PLP5-2-3MM-D54		N		P
	PLP5-2-3MM-S		N		P
	PLP5-2-3MM-S54		N		P
	PLP5-2-500		N		P
	PLP5-2-500 BE		N		P
	PLP5-2-500 BK		N		P
	PLP5-2-500 GN		N		P
	PLP5-2-500 GY		N		P
	PLP5-2-500 RD		N		P
	PLP5-2-500 YW		N		P
	PLP5-2-500-54		N		P
	PLP5-2-625		N		P
	PLP5-2-625 BE		N		P
	PLP5-2-625 BK		N		P
	PLP5-2-625 GN		N		P
	PLP5-2-625 GY		N		P
	PLP5-2-625 RD		N		P
	PLP5-2-625 YW		N		P
	PLP5-2-625-54		N		P
	PLP5-2-750		N		P

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION
PCN No: PCN-1081
Issue Date: 2/4/2025 (Updated 2/12/2025)

Parts Affected	PLP5-2-750 BE	Old Rev.	N	New Rev.	P
	PLP5-2-750 BK		N		P
	PLP5-2-750 GN		N		P
	PLP5-2-750 GY		N		P
	PLP5-2-750 RD		N		P
	PLP5-2-750 YW		N		P
	PLP5-2-750-54		N		P

Change Will Affect:

This change will affect the product specifications.

Description of Change:

The drawing has been revised to include:

- Tolerances for the light pipe body and ribs. (c.f. drawing)
- An updated recommended dimension for the mounting hole from 0.156 in to 0.154 in (+0.001 / -0.002 in).

Effective Date of Change: February 4, 2025

Reason for Change: Discrepancy in datasheet Information.

The PCN was updated on February 12, 2025, to remove items not affected by the change.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122