

Product Change Notice

PCN-S250603

Date of Publication: 2025/06/23

Description of Change:

1. Update **BIOS** of MTL-H SKUs from **V110 (1420061451)** to **V112 (1420063513)** to resolve intel TXT function issue.
2. Update **BIOS** of MTL-U SKUs from **X013 (1420059988)** to **V112(1420063495)** to resolve intel TXT function issue.
3. Update **EC FW** of all SKUs from **X0003 (1420059989)** to **V0100 (1420061450)**.

Affected Product Model No.:

SOM-A350 Standard P/N and related T-P/N.

Original P/N	Replacement P/N
1. BIOS (MTL-H): 1420061451 BIOS SOM-A350 0060V110 S CS: 531E W25R256JWP IQ	1. BIOS (MTL-H): 1420063513 BIOS SOM-A350 0060V112 CS:B6C3 W25R256JWP IQ
2. BIOS (MTL-U): 1420059988 BIOS SOM-A350 0060X013 CS:B423 W25R256JWP IQ	2. BIOS (MTL-U): 1420063495 BIOS SOM-A350 2060V112 CS:2F01 W25R256JWP IQ
3. EC FW: 1420059989 EC SOM-A350 X00_03 CS:67E5 A9620LIF2A(EIO-211)	3. EC FW: 1420061450 RDC SOM-A350 V0100 CS: 0EA8CF80 A9620LIF2A(EIO-

Potential impacts to customers:

PCB: no change required

BIOS: Change required

EC Firmware: Change required

OS: no change required

Driver: no change required

Function: no impact

Ordering Information:

No change

Impact of change & recommended action date:

[STD-P/N] Will adopt new BIOS and EC FW as replacements by **ECOM-227690** from 2025/6/27.

[T-P/N & Fixed BOM P/N users] Please get customers' approval and adopt new P/Ns for BIOS & EC FW as replacements.

Key Information & Milestones:

ECOM number: **ECOM-227690**

ECOM released date: **2025/6/27**

Issue by	PM: Clovia Hsieh
-----------------	------------------