



PRODUCT BULLETIN
Generic Copy

ISSUE DATE: 21-Sep-2012
NOTIFICATION: 15375
TITLE: DZ60 2M74K ERRATA DISTRIBUTION
EFFECTIVE DATE: 22-Sep-2012

DEVICE(S)

MPN
MC9S08DN16ACLC
MC9S08DN16AMLC
MC9S08DN16AMLF
MC9S08DN32ACLF
MC9S08DN32ACLH
MC9S08DN32AMLC
MC9S08DN32AMLF
MC9S08DN32AMLH
MC9S08DN32AVLF
MC9S08DN60ACLF
MC9S08DN60ACLH
MC9S08DN60AMLC
MC9S08DN60AMLF
MC9S08DN60AMLH
MC9S08DV16ACLC
MC9S08DV16ACLF
MC9S08DV16AMLC
MC9S08DV16AMLF
MC9S08DV32ACLC
MC9S08DV32ACLF
MC9S08DV32ACLH
MC9S08DV32AMLC
MC9S08DV32AMLCR
MC9S08DV32AMLF
MC9S08DV32AMLH
MC9S08DV48ACLC
MC9S08DV48ACLF

MC9S08DV48AC LH
MC9S08DV48AM LC
MC9S08DV48AM LF
MC9S08DV48AM LH
MC9S08DV60AC LC
MC9S08DV60AC LF
MC9S08DV60AC LFR
MC9S08DV60AC LH
MC9S08DV60AM LC
MC9S08DV60AM LF
MC9S08DV60AM LH
MC9S08DZ16AC LC
MC9S08DZ16AC LF
MC9S08DZ16AM LC
MC9S08DZ16AM LF
MC9S08DZ32AC LC
MC9S08DZ32AC LF
MC9S08DZ32AC LH
MC9S08DZ32AM LC
MC9S08DZ32AM LF
MC9S08DZ32AM LFR
MC9S08DZ32AM LH
MC9S08DZ48AC LC
MC9S08DZ48AC LF
MC9S08DZ48AC LH
MC9S08DZ48AM LC
MC9S08DZ48AM LF
MC9S08DZ48AM LH
MC9S08DZ60AC LC
MC9S08DZ60AC LF
MC9S08DZ60AC LH
MC9S08DZ60AM LC
MC9S08DZ60AM LF
MC9S08DZ60AM LH
S9S08DN16F2CLC
S9S08DN16F2CLF
S9S08DN32F2CLC
S9S08DN32F2CLCR

S9S08DN32F2CLF
S9S08DN32F2CLH
S9S08DN32F2MLC
S9S08DN32F2MLH
S9S08DN32F2VLC
S9S08DN32F2VLF
S9S08DN32F2VLFR
S9S08DN48F2CLF
S9S08DN48F2CLFR
S9S08DN48F2MLF
S9S08DN48F2MLFR
S9S08DN48F2MLH
S9S08DN48F2VLC
S9S08DN48F2VLF
S9S08DN48F2VLFR
S9S08DN60F2CLF
S9S08DN60F2CLH
S9S08DN60F2VLF
S9S08DN60F2VLH
S9S08DV16F2MLC
S9S08DV32F2MLC
S9S08DV32F2MLH
S9S08DV32F2VLC
S9S08DV32F2VLCR
S9S08DV48F2CLC
S9S08DV60F2CLH
S9S08DV60F2MLF
S9S08DZ16F2CLC
S9S08DZ16F2MLC
S9S08DZ16F2MLF
S9S08DZ16F2VLF
S9S08DZ32F2CLC
S9S08DZ32F2CLF
S9S08DZ32F2CLH
S9S08DZ32F2MLC
S9S08DZ32F2MLCR
S9S08DZ32F2MLF
S9S08DZ32F2MLFR

S9S08DZ32F2MLH
S9S08DZ32F2VLC
S9S08DZ32F2VLCR
S9S08DZ32F2VLF
S9S08DZ32F2VLH
S9S08DZ32F2VLHR
S9S08DZ48F2CLF
S9S08DZ48F2CLFR
S9S08DZ48F2CLH
S9S08DZ48F2MLF
S9S08DZ48F2MLH
S9S08DZ48F2VLF
S9S08DZ48F2VLFR
S9S08DZ60F2CLC
S9S08DZ60F2CLF
S9S08DZ60F2CLH
S9S08DZ60F2CLHR
S9S08DZ60F2MLC
S9S08DZ60F2MLCR
S9S08DZ60F2MLF
S9S08DZ60F2MLFR
S9S08DZ60F2MLH
S9S08DZ60F2MLHR
S9S08DZ60F2VLC
S9S08DZ60F2VLCR
S9S08DZ60F2VLH
S9S08DZ60F2VLHR

AFFECTED CHANGE CATEGORIES

- DEVICE SPECIFICATION / ERRATA

DESCRIPTION OF CHANGE

The 9S08DZ60 family of parts 2M74K mask set errata documentation is available now on Freescale website.

The errata documentation can be found at
http://www.freescale.com/webapp/sps/site/prod_summary.jsp?code=S08D&fmsp=1&tab=Documentation_Tab

The 2M74K errata document is the same with 1M74K errata except removed following errata: SE182-MCG-HighSIDDD3: High SIDDD3 at cold.

REASON FOR CHANGE

Initially published the errata documentation for 9S08DZ60 family of parts on 2M74K mask set.

ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)

There is no impact to device form, fit, function or reliability. There has been no change made to the current production device. The errata describes an existing condition that was identified on current production processes.

NOTE:

THE CHANGE(S) SPECIFIED IN THIS NOTIFICATION WILL BE IMPLEMENTED ON THE EFFECTIVE DATE LISTED ABOVE. To request further data or inquire about the notification, please enter a [Service Request](#)

For sample inquiries - please go to www.freescale.com

QUAL DATA AVAILABILITY DATE: 11-Nov-2009

QUALIFICATION STATUS: COMPLETED

QUALIFICATION PLAN:

N/A

RELIABILITY DATA SUMMARY:

N/A

ELECTRICAL CHARACTERISTIC SUMMARY:

N/A

CHANGED PART IDENTIFICATION:

N/A

SAMPLE AVAILABILITY DATE: 20-Sep-2012

ATTACHMENT(S):

External attachment(s) FOR this notification can be viewed AT:

[15375_MSE9S08DZ60_2M74K.pdf](#)
