	3 4	_ 5		6	7	8	
	Dallo 4 6	RECO	MMENDATION FOR	SOLDER PROCESS	SING		
har-flex straight female conn	ector RoHS (N)					
· ·		Solder	Solder paste recommendation The har-flex connectors are solderable with established lead-free SAC / SnNi solder but also leaded solder e.g. SnPb				
GENERAL INFORMATION							
		<u> </u>	ad plating				
No. of contacts	from 6 to 100poles, all even numbers	The ha	ar-flex connectors are	solderable on lead-	free pad surfaces like HAL, NiAu,	Immersion Sn.	
Contact spacing	1,27mm x 1,27mm [0,050"x0,050"]	Stenci	il recommendation				
Test Voltage	500V	The sol	Ider deposition has to	be placed on the pa	ad area of the contact solder tines	·	
Contact resistance	< 25 mOhm	Ideally,	the solder deposition	n has the same lengi	th-to-width ratio and center point I	ike the PCB pads.	
Insulation resistance	≥ 10x10^9Ω				ding on the thickness of the stenc		
Working current acc. to IEC 60512, at 70°C, 80% derating	see derating diagram				pertures to result in the required value in the signal pins is 0,094mm³, for the		
Working temperature range	-55°C +125°C		ample, this can be ach			c noid down it is 0,00mm.	
Termination technology	SMT		• •		Signal pins		
Reflow processing temperature	min. 150s > 217°C		Stencil thickness	DCB nod size	 	adoulated solder posts volume	
(acc. to ECA/IPC/JEDEC J-STD-075 Level PSL R0)	min. 30s > 240°C			PCB pad size	proposal stencil aperture size	calculated solder paste volume	
Clearance & creepage distance	0.4mm min.		120 µm	1,1 x 0,8 mm	1,05 x 0,75 mm	0,095 mm³	
Insertion force (depending on mating connector)	approximately 0,5N/contact	\dashv	150 µm	1,1 x 0,8 mm	0,99 x 0,72 mm	0,107 mm³	
Withdrawal force (depending on mating connector)	approximately 0,5N/contact				Hold-downs		
Mating cycles	PL1 : 500 mating cycles PL2 : 250 mating cycles	_	Stencil thickness	PCB pad size	proposal stencil aperture size	calculated solder paste volume	
RoHS - compliant	Yes		120 µm	2,5 x 1,2 mm	2,45 x 1,15 mm	0,338 mm³	
Leadfree	Yes		150 µm	2,5 x 1,2 mm	2,25 x 1,08 mm	0,365 mm³	
Working voltage acc. to to IEC 60664-1	100V / 150V (depending on installation category)	If a sten	ncil with lower thickne	ss shall be used ple	ease insure the minimum required	solder paste volume by enlarging the	
UL file acc. UL 1977	ECBT2.E102079	stencil a	aperture. Depending o	on the PCB design,	the solder depostion may protrude	e the PCB pads. But to achieve a go	
UL file acc. CSA-C22.2 (for Canada)	ECBT8.E102079	sealing	during solder paste p	rinting and to reduce	e the cleaning interval of the stend	cil, the aperture should be smaller	
PSL level acc. ECA/IPC/JEDEC J-STD-075	PSL R0		PCB pad about 10%	or 25µm encircling			
ISL level acc. ECA/IPC/JEDEC J-STD-020D MSL 1			Coplanarity of contacts				
	WIGE 1	All conr	nectors are tested for	coplanarity of conta	acts and are in the range of 6 pin	to 80 pin: ≤ 0.1mm	
INSULATOR MATERIAL	<u> </u>				82 pi	n to 100 pin: ≤ 0.15mm	
Material	LCP (liquid crystalline polymer)	Perform	nance level				
Color	Black		nance level 1 (recomm				
UL classification	UL94-V0	Initial 25	Initial 250 mating cycles, 10 days gas test (25°C / 75% r.h.) using H2S 10 ppb, NO2 200 ppb, CL2 10 ppb, SO2 200 pp				
	OLOT VO	I M		. 4 Th : - : - :	050)2 200 ppb, CL2 10 ppb, SO2 200 p	
Material group acc. IEC 60664-1	IIIa (175 ≤ CTI < 400)	—— Measure	ement of contact resis	stance. The remaini	ng 250 mating cycles are subject	to measurement of contact resistance	
Material group acc. IEC 60664-1		Measure and visu Visual ir	ement of contact resisual inspection. nspection. No abrasions	stance. The remaini	ng 250 mating cycles are subject shapped shapp	to measurement of contact resistance	
Material group acc. IEC 60664-1 CONTACT MATERIAL		Measure and visu Visual ir	ement of contact resisual inspection.	stance. The remaini	ng 250 mating cycles are subject	to measurement of contact resistance	
		Measurd and visu Visual in Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15	stance. The remaini	ng 250 mating cycles are subject	to measurement of contact resistance	
CONTACT MATERIAL	IIIa (175 ≤ CTI < 400) Copper alloy Sn	Measurd and visu Visual in Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15.	stance. The remainion of the contact finition	ng 250 mating cycles are subject sh through to the base material. N	to measurement of contact resistand lo functional impairment.	
CONTACT MATERIAL Contact material	IIIa (175 ≤ CTI < 400) Copper alloy	Measurd and visual in Part nur Perform Initial 12 Measurd	ement of contact resist ual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 da ement of contact resist	stance. The remainion of the contact finition of the contact finition	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO.	to measurement of contact resistance	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side	IIIa (175 ≤ CTI < 400) Copper alloy Sn Au over PdNi (acc. to Performance level)	Measure and visual in Part nur Perform Initial 12 Measure and visu	ement of contact resist ual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 day ement of contact resist ual inspection.	on of the contact finition of the contact finition 2	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject	to measurement of contact resistant lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistant	
CONTACT MATERIAL Contact material Plating termination zone	IIIa (175 ≤ CTI < 400) Copper alloy Sn Au over PdNi (acc. to Performance level)	Measure and visual in Part nur Perform Initial 12 Measure and visu Visual in	ement of contact resistant inspection. Inspection. No abrasion mber definition: 15 Inance level 2 Is mating cycles, 4 deferment of contact resistant inspection. Inspection. No abrasion inspection.	stance. The remaining on of the contact finition of the contact finition	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No.	to measurement of contact resistant lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistant	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacitation)	IIIa (175 ≤ CTI < 400) Copper alloy Sn Au over PdNi (acc. to Performance level)	Measure and visual in Part nur Perform Initial 12 Measure and visu Visual in	ement of contact resist ual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 day ement of contact resist ual inspection.	stance. The remaining on of the contact finition of the contact finition	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No.	to measurement of contact resistant lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistant	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capace The current carrying capacity is limited by maximum	Copper alloy Sn Au over PdNi (acc. to Performance level)	Measurd and visual in Part nur Perform Initial 12 Measurd and visual in Part nur Perform Perform	ement of contact resist ual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 defined a definition. nspection. nspection. No abrasion mber definition: 15 nance level S4	stance. The remainion of the contact finition of the contact finitions ays gas test (25°C / stance. The remainion of the contact finition of the conta	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No.	to measurement of contact resistant lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistant	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacitation)	Copper alloy Sn Au over PdNi (acc. to Performance level)	Measurd and visu Visual in Part nur Perform Initial 12 Measurd and visu Visual in Part nur Perform Defined	ement of contact resist ual inspection. Inspection. No abrasion mber definition: 15 Inance level 2 Inance level 2 Inspection. Inspection. Inspection. Inspection. Inspection. Inspection: 15 Inance level S4 I contact surface of m	stance. The remainion of the contact finition of the contact finitions gas test (25°C / stance. The remainion of the contact finition of the contact f	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No.	to measurement of contact resistant lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistant	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non	Copper alloy Sn Au over PdNi (acc. to Performance level)	Measurd and visu Visual in Part nur Perform Initial 12 Measurd and visu Visual in Part nur Perform Defined	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 definition. nspection. No abrasion mber definition: 15 nance level S4 I contact surface of momer definition: 15	stance. The remaining on of the contact finition of th	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No. 7,7+0,2µm PdNi	to measurement of contact resistance lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 ppt to measurement of contact resistance lo functional impairment.	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non interrupted current loaded contacts of connectors when	Copper alloy Sn Au over PdNi (acc. to Performance level)	Measure and visual in Part nur Perform Initial 12 Measure and visu Visual in Part nur Perform Defined Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 datement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level S4 I contact surface of momber definition: 15	stance. The remaining on of the contact finity of the contact finity of the stance. The remaining on of the contact finity of the co	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No. 7,7+0,2µm PdNi	to measurement of contact resistance lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistance lo functional impairment.	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non interrupted current loaded contacts of connectors when simultaneous power on all contacts is given, without	Copper alloy Sn Au over PdNi (acc. to Performance level)	Measure and visual in Part nur Perform Initial 12 Measure and visu Visual in Part nur Perform Defined Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 datement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level S4 I contact surface of material mber definition: 15 All Dimensions in material moriginal Size DIN Acceptable and programmed	stance. The remaining on of the contact finity	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No. 7,7+0,2µm PdNi	to measurement of contact resistance lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistance lo functional impairment. Ref. Sub.	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non interrupted current loaded contacts of connectors when simultaneous power on all contacts is given, without exceeding the maximum temperature.	Copper alloy Sn Au over PdNi (acc. to Performance level) Sity) The first four 1850 of 1950	Measure and visual in Part nur Perform Defined Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 datement of contact resisual inspection. nspection. No abrasion mber definition: 15 All Dimensions in moriginal Size DIN All rights reserved.	stance. The remaining on of the contact finity	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No. 0,7+0,2µm PdNi	to measurement of contact resistance lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistance lo functional impairment. Ref. Sub. Date State	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non interrupted current loaded contacts of connectors when simultaneous power on all contacts is given, without	Copper alloy Sn Au over PdNi (acc. to Performance level) Sity) The first four 1850 of 1950	Measure and visual in Part nur Perform Defined Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 datement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level S4 I contact surface of material mber definition: 15 All Dimensions in material moriginal Size DIN Acceptable and programmed	stance. The remaining on of the contact finity of the contact fini	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO2 ng 125 mating cycles are subject sh through to the base material. No. 0,7+0,2µm PdNi Ze tol. Inspected by Standardisation H0FFMANN	to measurement of contact resistance lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistance lo functional impairment. Ref. Sub. Date State 2014-05-23 Final Release Doc-Key / E	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non interrupted current loaded contacts of connectors when simultaneous power on all contacts is given, without exceeding the maximum temperature. Control and test procedures according to DIN IEC 60512-5	Copper alloy Sn Au over PdNi (acc. to Performance level) Sity) The first four 1850 of 1950	Measure and visual in Part nur Perform Defined Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 datement of contact resisual inspection. nspection. No abrasion mber definition: 15 All Dimensions in moriginal Size DIN A: All rights reserved Department EC PD - FR	stance. The remaining on of the contact finity of the contact fini	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO. ng 125 mating cycles are subject sh through to the base material. No. 0,7+0,2µm PdNi	to measurement of contact resistance lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 pp to measurement of contact resistance lo functional impairment. Ref. Sub. Date State 2014-05-23 Final Release Doc-Key / E	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non interrupted current loaded contacts of connectors when simultaneous power on all contacts is given, without exceeding the maximum temperature.	Copper alloy Sn Au over PdNi (acc. to Performance level) Sity) The first four 1850 of 1950	Measure and visu Visual in Part nur Perform Defined Part nur HARTING E	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 datement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level S4 I contact surface of material material size DIN A: All Dimensions in material original Size DIN A: All rights reserved. Department EC PD - FR	ays gas test (25°C / stance. The remaining on of the contact finition of the c	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO2 ng 125 mating cycles are subject sh through to the base material. No. 0,7+0,2µm PdNi The tol. Inspected by DE VANSSAY Paralle stacking height 6.25 and	to measurement of contact resistance lo functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 ppt to measurement of contact resistance lo functional impairment. Ref. Sub. Date State Final Release Doc-Key / E 100578057/UGG 500000074387 Rev. A	
CONTACT MATERIAL Contact material Plating termination zone Plating contact sliding side DERATING DIAGRAM acc. to IEC 60512-5 (Current carrying capacity is limited by maximum temperature of materials for inserts and contacts including terminals. The current capacity curve is valid for continuous, non interrupted current loaded contacts of connectors when simultaneous power on all contacts is given, without exceeding the maximum temperature. Control and test procedures according to DIN IEC 60512-5	Copper alloy Sn Au over PdNi (acc. to Performance level)	Measure and visual in Part nur Perform Defined Part nur	ement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level 2 25 mating cycles, 4 datement of contact resisual inspection. nspection. No abrasion mber definition: 15 nance level S4 I contact surface of material material size DIN A: All Dimensions in material original Size DIN A: All rights reserved. Department EC PD - FR	ays gas test (25°C / stance. The remaining on of the contact finition of the c	ng 250 mating cycles are subject sh through to the base material. No. 75% r.h.) using H2S 10 ppb, NO2 ng 125 mating cycles are subject sh through to the base material. No. 0,7+0,2µm PdNi Ze tol. Inspected by Standardisation H0FFMANN	to measurement of contact resistance. It is functional impairment. 2 200 ppb, CL2 10 ppb, SO2 200 ppp to measurement of contact resistance. It is functional impairment. Ref. Sub. Date State 2014-05-23 Final Release Doc-Key / E 100578057/JGG 500000074387	

